

Permitting and Inspections Department Michael A. Russell, MS, Director

January 31, 2018

DOWTOWN LODGING LLC PO BOX 10250 PORTLAND, ME 04104

CBL: 026 F015001

Located at: 273 CUMBERLAND AVE

Certified Mail 7014 1820 0001 4049 7413

Dear DOWTOWN LODGING LLC,

An evaluation of the above-referenced property on 01/24/2018 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 30 days of the date of this notice. A re-inspection of the premises will occur on 03/01/2018 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

/s/

Matthew Sarapas

Code Enforcement Officer

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

			1110	pection	Violati			
Owner/Manager DOWTOWN LODGING LLC				Inspector Matthew Sarapas		Inspection Date 1/24/2018		
Location CBL			Status		Inspection Type			
273 CUMBERLAND AVE		026 F015001		Violations Exist		Inspection		
Code	<u>Ir</u>	ıt/Ext	Floor	Unit No.	Area	Compliance Date		
1) 54.315 Violation:	NFPA 101- 29 SECTION 7.9).2.9.1 E SHALL	EMERGENC . BE PROVII	Y LIGHTING DED IN ALL	; EMERGEI BUILDINGS	NCY LIGHTING IN ACCORDANCE WITH WITH MORE THAN 25 ROOMS.		
Notes:	Emergency light on third floor in the vicinity of room 3-9 is weak and should be repaired or replaced							
2) 54.250			,,					
Violation:	NFPA 101- 29.2.5.1 ARRANGEMENT OF MEANS OF EGRESS; ACCESS TO ALL REQUIRED EXITS SHALL BE IN ACCORDANCE WITH SECTION 7.5.							
Notes:	No separation exists between exit stairs. Owner shall apply for a permit within 30 days to create separation between egress stairs. Life safety plan reviewer for the city is willing to conduct a site visit to determine separation scheme to fire rate egress stairwells.							
3) 54.575		,						
Violation:	NFPA 101- 29.7.4.1 FLOOR DIAGRAMS SHALL BE POSTED; A floor diagram reflecting the actual floor arrangement, exit locations, and room identification shall be posted in a location and manner acceptable to the authority having jurisdiction on, or immediately adjacent to, every guest room door in hotels and in every resident room in dormitories.							
Notes:	1.000							
4) 54.470								
Violation:	NFPA 101- 29.3.6.3.1 UNPROTECTED OPENINGS PROHIBITED FOR EXIT CORRIDORS; UNPROTECTED OPENINGS, OTHER THAN THOSE FROM SPACES COMPLYING WITH 29.3.6.3.2, SHALL BE PROHIBITED IN EXIT ACCESS CORRIDOR WALL AND DOORS.							
Notes:	Third floor has two skylight shafts with unrated walls that lead into the cockloft.							
5) 54.460								
Violation:	NFPA 101- 29.3.6.2.3 DOORS TO EXIT CORRIDORS SHALL BE SELF-CLOSING; DOORS THAT OPEN ONTO EXIT ACCESS CORRDIORS SHALL BE SELF-CLOSING AND SELF-LATCHING.							
Notes:	Unit doors need to self close throughout.							
6) 54.350								
Violation:	NFPA 101- 29.3.2.2.1 HIGH HAZARD ROOM SEPERATED PER SECTION 8.7; ANY HAZARDOUS AREA SHALL BE PROTECTED IN ACCORDANCE WITH SECTION 8.7							
Notes:	Laundry room requires one hour separation or a domestic sprinkler head over gas fired dryer.							
7) 54.440 Violation:	protected thro	oughout able fire	with an app extinguishe	roved, super	vised autom	VIDED; In buildings other than those atic sprinkler system in accordance with pecified in 9.7.4.1 in hazardous areas		

Multiple extinguishers noted with expired inspection tags.

Notes:

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date
DOWTOWN LODGING LLC	;	Matthew Sarapas	1/24/2018
Location	CBL	Status	Inspection Type
273 CUMBERLAND AVE	026 F015001	Violations Exist	Inspection

8) 54.420

Violation: NFPA 101- 29.3.4.5 SMOKE ALARMS INSTALLED IN GUEST ROOMS PER 9.6.2.10; AN

APPROVED SINGLE-STATION SMOKE ALARM SHALL BE INSTALLED IN ACCRDOANCE WITH 9.6.2.110 IN EVERY GUEST ROOM AND EVERY LIVING AREA AND SLEEPING ROOM WITHIN A

GUEST SUITE.

Notes: Missing or disabled smoke alarms noted in multiple rental rooms. Each sleeping room requires a

hardwired battery back up photoelectric smoke alarm. Rooms: 1-2, 1-5, 2-2, 3-10, 3-2, 3-3

9) 54.335

Violation: NFPA 101-29.3.1.1 PROTECTION OF VERTICAL OPENINGS; VERTICAL OPENINGS SHALL

COMPLY WITH 29.3.1.1.1 THROUGH 29.3.1.2.

Notes: As noted in violations of 12/1/2017, there are three large (2'x2') shafts that run from basement to the

roof. Must be one hour fire rated.

10) 6-113.(d)

Violation: EXTENSION CORDS.; No temporary wiring shall be used except extension cords which run directly

from portable electrical fixtures to convenience outlets, ceiling or wall-type fixtures and which do not lie under rugs or other floor coverings, nor extend through, doorways, transoms or similar openings

through structural elements.

Notes: Room 2-10 is using multiple interconnected extension cords as permanent wiring.

11) 69.20

Violation: PORTLAND FIRE DEPARTMENT CHAPTER 10 SECTION 12 KNOX BOX REQUIRED; KNOX

BOXES ARE REQUIRED FOR ALL BUILDINGS WITH FIRE ALARM OR SUPPRESSION SYSTEMS.

Notes: As noted on 12/1/2017 inspection report, building is equipped with a fire alarm, must have a knox box

installed.

12) 69.25

Violation: PORTLAND FIRE DEPARTMENT CHAPTER 10 4.6.1, 4.6.2 UNIT/SUITE NUMBERS NOT MARKED;

4.6.1 RESIDENTIAL UNITS SHALL BE DESIGNATED USING NUMERALS.

4.6.2 THE FIRST NUMERAL OF EACH RESIDENTIAL UNIT SHALL BE THE FLOOR DESIGNATION.

Notes: All sleeping rooms require appropriate labeling.

Comments: Violations from 12/1/17 fire department inspection remain open. Additional violations noted.