

LINCOLN PARK - PORTLAND, MAINE

IRON FENCE RESTORATION - PHASE 1


HISTORIC PRESERVATION REVIEW - FEB 7, 2018

Owner:

CITY OF PORTLAND

PARKS, RECREATION & FACILITIES

www.portlandmaine.gov



Engineer:

RESURGENCE

ENGINEERING & PRESERVATION, INC.

ALFRED H. HODSON III, P.E.
JOHN D. TURK, AIA

WWW.RESURGENCEENGINEERING.COM


PORTLAND, MAINE

207.773.4880

Advocate:

FRIENDS OF LINCOLN PARK

www.lovelincolnpark.org



GENERAL NOTES & SITE PLAN - BASE BID

PHOTOS OF TYPICAL CONDITIONS

S-0.1 General Notes - Base Bid

S-0.2 Site Plan - Base Bid

S-0.3 Site Survey Plan - Base Bid

S-0.4 Site Details - Base Bid

IRON RESTORATION KEY ELEVATIONS

S-1.1 Congress Street Fence Sections - Base Bid

S-1.2 Congress Street Fence Sections - Base Bid

S-1.3 Pearl Street Fence Sections - Alt. 1

S-1.4 Pearl Street Fence Sections - Alt. 1

S-1.5 Federal Street Fence Sections - Alt. 2

S-1.6 Federal Street Fence Sections - Alt. 2

S-1.7 Federal Street Fence Sections - Alt. 2

S-1.8 Franklin Street Fence Sections - N.I.C.

S-1.9 Franklin Street Fence Sections - N.I.C.

IRON RESTORATION DETAILS - BASE BID

S-2.1 Congress Street Gate and Typical Railing

S-2.2 Typical New Casting Details

S-2.3 Typical New Fence Post Details

S-2.4 Typical New Top Rail Connection Details

S-2.5 Typical New Top & Bottom Rail Details

S-2.6 Typical New Gate Casting Details

GRANITE RESTORATION

S-3.1 Granite Entry Pier Treatments - Base Bid

S-3.2 Granite Entry Pier Treatments - Base Bid & N.I.C.

S-3.3 Granite Entry Pier Treatments - N.I.C. & Alt. 2

S-3.4 Granite Entry Pier Treatments - Alt. 2 & Base Bid

S-3.5 Typical Granite Treatment Details - Phase 1

