



TYPICAL CHIPPING - SECTION REPAIR



PAINT & RUST STAINING - CLEANING



TYPICAL DAMAGED GRANITE - SECTION REPAIR



TYPICAL SANBLASTING - RETOOLING



OUT OF SQUARE & PLUMB - REALIGN



MISSING GATE PIECES - RECAST REPLACEMENTS



TYPICAL DAMAGED FENCE POST - CUT REPLACEMENT



TYPICAL UPPER RAIL - NEW ANCHOR METHOD



MISSING BOTTOM RAIL SECTION - RECAST REPLACEMENT