IS-FBC: Building Design Standards (BDS) More **Does Not Complies** Info Comply N/A **Comments BUILDING DESIGN** Review (2/17/16) Caitlin Cameron, Rick Knowland, Jean Fraser **STANDARDS (BDS)** 1. Neighborhood Context \boxtimes П Intent Guidelines The material palette appears dark compared to the context – samples? The review panel was concerned about the building in context \boxtimes of Hampshire Street, attention should be given to those parts of the building visible from the street. 2. Massing & Proportion The panel is concerned about the scale of the Intent garage façade on Franklin - the proportion of \square the garage to the overall building is quite tall and very little makes the two-story wall comfortable at pedestrian scale. Guidelines Bring more emphasis to the corner: see sketch attached for notes. The stepbacks help to mitigate the scale of the new, large building \boxtimes compared with the smaller context. Stepback at back corner would alleviate the scale and height impacts for the 2 and 3-story buildings. \boxtimes Standard 2.1 3. Articulation & Composition The Franklin garage façade does not, yet, Intent \boxtimes meet the articulation standards. \boxtimes Guidelines This standard is not met for the garage façade: Standard 3.1: 3 required \boxtimes see comments in Section 8 \boxtimes Standard 3.2 Franklin garage façade – more articulation is Standard 3.3: Blank Wall \boxtimes requested to break up the blank wall.

		Complies	More Info	Does Not Comply	N/A	Comments
4.	Fenestration					
	Intent	\boxtimes				
	Guidelines					Consider adding fenestration to the garage level – façade is lacking variation and scale. Why does the fenestration jog at the corner of Newbury and Franklin?
	Standard 4.1 (UA only)				\boxtimes	
	Standard 4.2	\boxtimes				
	Standard 4.3		\boxtimes			What kind of glass?
	Standard 4.4		\boxtimes			Will there be spandrel glass used?
5.	Building Materials	_		_		
	Intent					
	Guidelines					See comments in Section 3 and 8 regarding Franklin garage façade.
6.	Building Entries					
	Intent					
	Guidelines					More information on the entry is requested – lighting, side lights? The entry door and windows are too diminutive for a principal entry – more emphasis.
	Standard 6.1					Principal entrance faces Newbury Street.
	Standard 6.2 (UA only)				\boxtimes	
	Standard 6.3					
	Standard 6.4				\boxtimes	
	Standard 6.5					
	Standard 6.6					
	Standard 6.7: Frequency			\bowtie		At least one entry is required on each facade

	Complies	More Info	Does Not Comply	N/A	Comments
7. Roof Lines					
Intent	\boxtimes				
Guidelines					
Standard 7.1					
Standard 7.2	\boxtimes				
8. Structured Parking					
Intent			\boxtimes		The Franklin Street garage façade does not meet the intent of minimizing the impact of a two-story garage on the street. No part of the façade is activated.
Guidelines					The current design of the Franklin garage façade does not use materials and architectural detailing found in the floors above – the result is a base that does not feel integrated into the design. Suggestions: bring the plane changes and cladding materials from the residential floors lower onto the façade. Refer to the sketch for further notes and clarification.
Standard 8.1					The review panel feels this standard is not yet met – there is a lack of articulation and visual interest on a long and prominent façade. Suggestions: carry the plane changes all the way down the façade; bring the cladding material further down the façade; incorporate openings or windows into the upper parking deck; chose a base material color that better relates to the upper floors; incorporate lighting; incorporate landscaping. The panel was especially concerned with CPTED when it comes to visibility and safety along this façade. Refer to the sketch for further notes and clarification.
Standard 8.2	\boxtimes				
Standard 8.3					
Standard 8.4					