

2-9-05

Imposed Steel Column on
left end corner of building/steel corner
beam being re-inforced with steel plates
welded in place. Special inspection being
done they will fax us copies of those

4/22/05 Closed. Over