



Jeff Levine, AICP, Director
Planning & Urban Development Department

Tammy Munson, Director
Inspections Division

Air Velocity within the duct system _____

Grease accumulation prevention system: _____

Cleanouts: Side of Elbow on 1st Floor

Grease Duct enclosure: _____

Exhaust Termination: Roof Wall _____

Fire Suppression System: By Owner's Model FP-18 / R-102 ASEFC

Exhaust fan mounting and clearance from the roof / wall or Combustibles: _____

Per NFPA 96

Exhaust fan distance from property lines: Roof Discharge

Exhaust fan distance from other vents or openings: N/A

Exhaust fan distance from adjacent buildings: N/A

Exhaust fan height above adjoining grade: _____

X

3. Hood Specs

(cost - \$29,585)

Style of Hood: ELX-BB-MP-AS-120 Exhaust w/ Return Air Plenum

Type of Filter: S/S Grease Extraction Baffle filters

Height of filter above nearest cooking surface: 6"

Capacity of hood CFM: 5524 CFM

Make up Air system description and capacity: _____

By Others: We only provided the plenum