

Inspection Services
Michael J. Nugent
Manager

Department of Urban Development
Joseph E. Gray, Jr.
Director



CITY OF PORTLAND

June 16, 1999

Denis Marchese, Frank Collins
Patrick Lops and Geo. Heffren
F. Parker Reidys'
83 Exchange St.
Portland ME 04101

CBL: 032-D-004

Hand Delivery

Dear Sirs:

Due to the ongoing problem with the grease originating from your establishment and discharging into the city sewer pursuant to Chapter 238, Section I.G.U. and Section 8 of the State of Maine Internal Plumbing Rules, you are hereby ordered to install a larger grease interceptor.

You are given 30 days from the receipt of this letter to install the interceptor. Failure to comply with this order could result in suspension of your food service license and/or court action.

Sincerely,

Arthur Rowe
Code Enforcement Officer

/sap