



FACADE RENOVATION NOTES:

- (A) EXISTING STOREFRONT TO BE REPAIRED, NEW CLEAR GLAZING, FRAMES & SASHES.
- (B) METAL DECORATIVE COLUMNS WITH GRANITE PIERS TO REMAIN. NEW PAINT AT COLUMNS.
- (C) ENTRY TO BE RECONFIGURED.
- (D) WOOD PANEL STOREFRONT TO BE REMOVED.
- (E) ENTRY STAIRS TO BE REMOVED.
- (F) STEEL FREEZE TO REMAIN, NEW PAINT.
- (G) NO WORK AT BRICK FACADE, TYP.
- (H) EXISTING IRON BARS AT BASEMENT BULKHEAD WINDOWS TO BE REMOVED.
- (I) PRESERVE GRANITE BASES, TYP.
- (J) EXISTING DOUBLE HUNG WINDOWS TO REMAIN, TYP.
- (K) EXISTING DOUBLE HUNG WINDOWS TO BE REPLACED WITH WOOD SASH REPLACEMENT KITS, SUBMISSION FOR STAFF REVIEW BY WINDOW REPRESENTATIVE.
- (L) EXISTING SIGNAGE LOCATION (SEPARATE SIGN PERMIT BY TENANT)




WS1
HP-1.1
3/4"=1'-0"

Port Property
MANAGEMENT



MARK
MUELLER
ARCHITECTS



A- 1.1