

FACADE RENOVATION NOTES:

(A) EXISTING STOREFRONT TO BE REPAIRED, NEW CLEAR GLAZING, FRAMES & SASHES.

B METAL DECORATIVE COLUMNS WITH GRANITE PIERS TO REMAIN. NEW PAINT AT COLUMS.

 $\langle C \rangle$  ENTRY TO BE RECONFIGURED.

 $\langle \overline{\mathsf{D}} \rangle$  WOOD PANEL STOREFRONT TO BE REMOVED.

 $\langle \overline{D1} \rangle$  ENTRY STAIRS TO BE REMOVED.

 $\langle E \rangle$  STEEL FREEZE TO REMAIN, NEW PAINT.

 $\langle F \rangle$  NO WORK AT BRICK FACADE, TYP.

G EXISTING IRON BARS AT BASEMENT BULKHEAD WINDOWS TO BE REMOVED

 $\langle H \rangle$  PRESERVE GRANITE BASES, TYP.

EXISTING DOUBLE HUNG WINDOWS TO REMAIN, TYP.

EXISTING DOUBLE HUNG WINDOWS
TO BE REPLACED WITH WOOD SASH
REPLACMENT KITS, SUBMISSION FOR STAFF
REVIEW BY WINDOW REPRESENTATIVE.

EXISTING SIGNAGE LOCATION (SEPARATE SIGN PERMIT BY TENANT)

MARK L.
MUELLER
No. 2737

OF
MILLIAN

OF
M

A - 1.2

JANUARY 17, 2014

M A R K
MUELLER
ARCHITECTS