CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Inspection Date

Inspector

TF	TRUSSELL PROPERTIES LLC				Suzanne Hunt			3/14/2007	
Locatation CBL			Status			Inspection Type			
84	PARK AVE		048 B005001	Re-Inspe	ct 10 Days		Housing-Inspection		
	Code	Int/Ext			Floor	Unit No.	Area	Compliance Date	
1)	6-108.1	Exterior			3	3	roof/		
	Violation:	Foundations	lls, roofs						
	Notes: There is a hole approximtely 4 inches square above the ceiling tiles on a horizontal was the exterior air must be repaired. Sheathing and or propeer covering required inside a								
2)	6-108.1	Interior			3	3	Bathroom		
,	Violation: Foundations cellars, exterior walls, roofs								
Notes: The pipe located above the ceiling tiles may be leaking, All leaks into the bath							nto the bathroo	om must be repaired.	
3)	6-108.1	Exterior			3	3	Bathroom		
	Violation:	Foundations cellars, exterior walls, roofs							
	Notes:	The leak resulting in dripping water into the bathroom must be repaired							
4)	6-108.3	Interior			3	3	Bedroom		
	Violation:	Exterior windows, doors and skylights							
	Notes:	The window in the front window, (in the front room toward Park Ave.) must be repaired. Window weight springs are missing or broken.							
5)	110.26 (B)	Interior			1	4			
	Violation:	NEC 2005/NFPA 70							
	Notes:	No hard wire smoke detectors in unit # 4 . Building code requires One smoke detector in each bedroom and 1 in the vicinity of the bedrooms in each unit, interconnected within the unit with battery back- up.							

3

3

Hallway

Comments:

6) 110.26 (B)

Notes:

Violation:

Interior

NEC 2005/NFPA 70

smoke detector in hallway unit #3 is missing a battery.

Owner/Manager