CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

December 7, 2017

Location	CBL	Inspection Date	
22 SHERMAN ST	036 F006001	11/9/2017	
Inspector	Inspection Type	Status	
1 -		Status	

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 12/30/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101-7.2.4.3.1 FIRE BARRIER REQUIRES MAINTENANCE; Fire barriers separating buildings or areas between which there are horizontal exits shall have a minimum 2-hour fire resistance rating, unless otherwise provided in 7.2.4.4.1, and shall provide a separation that is continuous to the finished grounded level. 1) Patch the hole in the wall (caused by the door handle) in the front stairwell. 2) Patch the	//
damaged sheet rock above the basement stairs.	
NFPA 10- 7.2.4.4 FIRE EXTINGUISHER INSPECTION TAG; Where manual inspections are conducted, records for manual inspections shall be kept on a tag or label attached to the fire extinguisher, on an inspection checklist maintained on file, or by an electronic method. Extinguishers in the stairwells must be inspected and tagged or removed.	//
NFPA 1 EXCESSIVE/DISORDERLY STORAGE; Reference NFPA 1 for excessive fuel-load.	/ /
Remove all storage from the front and rear stairwells on all levels.	//
NFPA 70- 4.10.8 DEFECTIVE LIGHT FIXTURE; Luminaries shall be installed such that the connections between the luminaire conductors and the circuit conductors can be inspected without requiring the disconnection of any part of the wiring unless the luminaries are connected by attachment plugs and receptacles. Multiple light fixtures in the basement are missing lightbulbs.	//
NFPA 101- 31.3.2.1.1 BOILER PROTECTION REQUIRED; The areas described in Table 31.3.2.1.1 shall be protected as indicated: Boiler and fuel-fired heater rooms serving more than a single dwelling unit (minimum separation/protection is 1 hour or sprinklers) Install a domestic sprinkler head above the gas water heaters in the basement. 1 centrally located head will be sufficient.	//

Violation		Proposed Date of Completion
buildings or areas between wh resistance rating, unless other continuous to the finished grou	RRIER REQUIRES MAINTENANCE; Fire barriers separating ich there are horizontal exits shall have a minimum 2-hour fire wise provided in 7.2.4.4.1, and shall provide a separation that is inded level. wall needs to be repaired near piping	//
FINAL DATE OF COMPLETE	, , , ,	/ /
FIRE PREVENTION BUREAU	J RE-INSPECTION OF COMPLETED VIOLATION(S)	//
	nt to reject or modify any proposed plan of action, and may nical capacity to complete the proposed plan. Please contact TION	-
understand that I must contain is entirely within the Bureau I further understand that it is	ions listed within the timeframes provided. If I require addition the Fire Prevention Bureau prior to the deadline to require's discretion to grant or deny. is my responsibility to schedule a reinspection of my propertion. My failure to schedule a reinspection shall be deemed and redied.	test an extension, which rty once the violations
If I fail to comply with this a	greement, I understand that I am liable for penalties pursues §§ 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	