

SECTION 00300

INFORMATION AVAILABLE TO BIDDERS

1.1 REPORT OF SUBSURFACE AND FOUNDATION INVESTIGATION

A. Report of subsurface investigations and recommendations Sebago Technics.

1. This report identifies properties of below grade conditions, prepared primarily for the use of the Architect/Engineer.
2. This report, by its nature, cannot reveal all conditions that exist on the site. Should subsurface conditions be found to vary substantially from this report, changes in the design and construction of foundations may be considered so as to address any concerns, with resulting credits or expenditures to the Contract Price/Sum accruing to the Owner. The construction manager shall work with the owner toward expeditious resolution of any unforeseen site issues.

1.2. PHASE I ENVIRONMENTAL SURVEYS

A YMCA – Parking Lot Portion of Lot 22 Map 6 Forest Avenue

1.3 Sample Construction Sign

... END OF SECTION