Portland, Maine



Yes. Life's good here.

Danielle P. West-Chuhta Corporation Counsel

Anne M. Torregrossa Associate Counsel Michael I. Goldman Associate Counsel

July 14, 2016

NOTICE OF INTENT TO PROSECUTE

Jean C. Simmons 39 Mona Road Portland, Maine 04103

RE:

94 Portland

CBL036 H003001

To Whom it May Concern,

Please see the attached Inspection Violations. The City of Portland Fire Department has referred this matter to me for prosecution. In order to avoid prosecution, you must submit to Fire Prevention Bureau a plan of action to remedy the violations no later than **July 29, 2016**.

YOUR FAILURE TO SUBMIT A PLAN OF ACTION WITHIN THE TIMEFRAME PROVIDED WILL RESULT IN LEGAL ACTION AND THE IMPOSITION OF CIVIL PENALTIES.

Please feel free to contact Tori Ross of the Fire Prevention Bureau at (207)874-8400 with any questions. I look forward to your anticipated cooperation and appreciate your efforts to help keep the citizens of Portland safe.

Sincerely,

Ánne M. Torregrossa

Associate Corporation Counsel

City of Portland

CITY OF PORTLAND PORTLAND FIRE DEPARTMENT

380 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager SIMMONS JEAN C		Inspector Scott True	Inspection Date 5/29/2016
Location	CBL	Status	Inspection Type
94 PORTLAND ST	036 H003001	Failed	Fire Company-FP Routine Inspec

Code Int/Ext Floor Unit No. Area Compliance Date

1) 91.20

Violation: NFPA 70- 590.6 EXTENSION CORDS; Ground-fault protection for personnel for all temporary wiring

installations shall be provided to comply with 590.6(A) and (B). This section shall apply only to temporary wiring installations used to supply temporary power to equipment used by personnel during construction, remodeling, maintenance, repair, or demolition of buildings, structures, equipment, or

similar activities.

Notes: EXTENSION CORD USED AS PERMANENT WIRING IN BASEMENT

2) 6.005

Violation: NFPA 70- 4.10.8 DEFECTIVE LIGHT FIXTURE; Luminaries shall be installed such that the

connections between the luminaire conductors and the circuit conductors can be inspected without requiring the disconnection of any part of the wiring unless the luminaries are connected by attachment

plugs and receptacles.

Notes: WATER DRIPPING INTO LIGHT FIXTURE IN BASEMENT BY FURNACE

Comments: violations noticed at a call not full inspection