


582 Congress (Front) – Store front redesign and restoration



Work to be done:

- Demo side column veneers and see what condition original iron columns are underneath wood paneling. If in good condition, restore. If not, replace with similar to existing
- Reduce entry vestibule to 24" deep and 48" wide
- Front display windows to be enlarged (dimensions to be based on structural considerations and side iron columns)
- Bottom façade base to be replaced with similar recessed wooden panel fronts in black at same height to existing
- Changes to lighting and signage not part of this building permit
- See notes from historical preservation board meeting held on 12 February, 2018