CITY OF PORTLAND FIRE PREVENTION BUREAU

MAY 15 2017

By Electronic

380 Congress Streef, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

September 30, 2016

| Responsible Party: Beaver Block, LLC 796 Forest Ave | | |
|---|---------------------------------------|-----------------------------|
| Portland, Maine 04103 Location 0496 CONGRESS ST (Subway) | CBL 037 1001001 | Inspection Date 9/8/2016 |
| Inspector Alan Greene | Inspection Type FP Routine Inspection | Status Failed |

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must complete the proposed date of completion column by proposing a reasonable timeframe to remedy each violation. This form must be received by the Fire Prevention Bureau no later than 10/15/2016. The Bureau reserves the right to reject or modify any proposed plan of action, and may require evidence of sufficient financial and technical capacity to complete the proposed plan. Please contact the Bureau with any questions.

YOUR FAILURE TO SUBMIT A PLAN OF ACTION BY THE DATE PROVIDED, OR TO CORRECT ANY VIOLATION WITHIN THE APPLICABLE TIME FRAME, MAY RESULT IN LEGAL ACTION AGAINST YOU, THE IMPOSITION OF CIVIL PENALTIES, AND THE PURSUIT OF OTHER LEGAL REMEDIES.

| Violation | Proposed Date of Completion |
|---|-----------------------------|
| NFPA 10-7.1.1 FIRE EXTINGUISHERS NEED ANNUAL SERVICE; The owner or designated agent or occupant of a property in which fire extinguishers are located shall be responsible for inspection, maintenance, and recharging. All | 7/31/17 |
| 1-14-3.2 EMERGENCY LIGHTING AND EXIT SIGNS SHALL BE TESTED; EMERGENCY LIGHTING FACILITIES AND EXIT SIGNS SHALL BE TESTED MONTHLY FOR 30 SECONDS AND ANNUALLY FOR 90 MINUTES, AND WRITTEN RECORDS SHALL BE MAINTAINED. Not functioning | 7/3/17 |
| NFPA 101-7.2.8.6.2 FIRE ESCAPE REQUIRES REPAIR; The authority having jurisdiction shall be permitted to approve any existing fire escape stair that has been shown by load test or other satisfactory evidence to have adequate strength. Exterior stairs from roof to roof (4th floor) in disrepair. | 7/31/17 |
| NFPA 70- ARTICLE 590.6 EXT. CORD USED FOR PERMENANT WIRING; Ground-fault protection for personnel for all TEMPORARY wiring installations shall be provided to comply with 590.6 (A) and (B). This section shall apply only to temporary wiring installations used to supply temporary power to equipment used by personnel during construction, remodeling, maintenance, repair, or demolition of buildings, structures, equipment or similar activities. 3 rd floor server closet, power strip. | 7/31/17 |

| Violation | | Proposed Date of Completion |
|-------------------------------|---|-----------------------------|
| InteriorWall and Ceiling Fini | HOLE IN CEILING NEEDS REPAIR; sh Interior walls and ceiling finish materials complying with 10,2 s: 1) Exit encloures Class A or class B 2) Lobbies and B 3) Other spaces Class A, or Class B, or Class C | 7/3/17 |

VIOLATOR CERTIFICATION

I agree to remedy the violations listed within the timeframes provided. If I require additional time to comply, I understand that I must contact the Fire Prevention Bureau prior to the deadline to request an extension, which is entirely within the Bureau's discretion to grant or deny.

I further understand that it is my responsibility to schedule a reinspection of my property once the violations have been remedied to do so. My failure to schedule a reinspection shall be deemed an admission that the violations have not been remedied.

| If I fail to comply with this agreeme Portland Code of Ordinances §§ 1-1 | ent, I understand that I am liable for penalties pursuant to the City of 5 and 10-25, and 30-A M.R.S. § 4452 and may be subject to further legal |
|---|--|
| action. 5/10/17 | Kon () Telles |
| Date | Responsible Party |
| Date | Responsible Party |
| SEEN AND AGREED | CHOT DR SH 17 |
| Date | Fire Prevention Bureau |