## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

January 16, 2018

JOHN QUIRK 4 SCHOONER RD SCARBOROUGH ME 04074

Location	CBL	Inspection Date	
126 SPRING ST	039 D002001	11/29/2017	
Inspector	Inspection Type	Status	
Sean Donaghue	FP Routine Inspection	Failed	

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 2/15/2018.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101-7.2.4.3.1 FIRE BARRIER REQUIRES MAINTENANCE; Fire barriers separating buildings or areas between which there are horizontal exits shall have a minimum 2-hour fire resistance rating, unless otherwise provided in 7.2.4.4.1, and shall provide a separation that is continuous to the finished grounded level.  Basement hallway open to the backside of an interior wall of Unit 2, insulation visible, please close basement hallway in with properly rated sheetrock	//
NFPA 101- 31.3.1.1.1 VERTICAL OPENINGS NOT FIRE RATED; Vertical openings shall be enclosed or protected in accordance with Section 8.6.  Attic access in main stairwell top floor and in Unit 6 (common area and closet) needs to provide proper fire rating, currently fiberboard	//
NFPA 101- 7.2.1.8.1 FIRE DOORS MUST BE SELF- OR AUTO-CLOSING; A door leaf normally required to be kept closed shall not be secured in the open position at any time and shall be self-closing or automatic-closing in accordance with 7.2.1.8.2, unless otherwise permitted by 7.2.1.8.3.  Basement door must be properly rated fire door and must self close. A tag displaying the fire rating must be visible.	//
NFPA 101- 7.1.8 STAIR GAURDS MUST BE REPAIRED; Guards in accordance with 7.2.2.4 shall be provided at the open sides of means of egress that exceed 30 inches above the floor or the finished ground level below.  Bollisters on 3rd floor missing. Owner requested notation of Windham Millwork in this violation for possible assistance in securing matching replacements to existing bollisters	//
NFPA 70 MISSING BOX COVERS; Refer to NFPA 70, National Electrical Code, on standards for missing box covers.  Basement at the base of stairs	//

Violation		Proposed Date of Completion
outdoor unprotected gas lines.	rside GAS LINE; See NFPA 54 regarding requirements for conly width of sidewalk, please install bollards to protect gas	//
FINAL DATE OF COMPLETED VIOLATION(S)		//
FIRE PREVENTION BUREAU	RE-INSPECTION OF COMPLETED VIOLATION(S)	//
	to reject or modify any proposed plan of action, and may ical capacity to complete the proposed plan. Please contaction	
•	ons listed within the timeframes provided. If I require add to the Fire Prevention Bureau <u>prior to the deadline</u> to req to discretion to grant or deny.	- ·
	s my responsibility to schedule a reinspection of my propo My failure to schedule a reinspection shall be deemed a edied.	
	reement, I understand that I am liable for penalties purses $\S$ \$\ \ 1-15 and 10-25, and 30-A M.R.S. \ \ \ 4452 and may be	• •
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	