Portland, Maine



Yes. Life's good here.

Danielle P. West-Chuhta Corporation Counsel

Michael I. Goldman Associate Counsel Anne M. Torregrossa Associate Counsel Victoria E. Morales Associate Counsel

October 11, 2016

NOTICE OF INSPECTION

To Whom it May Concern,

On September 12, 2016, the City of Portland Fire Department conducted a preliminary inspection of your property but was unable to conduct a full inspection. Please contact the Fire Prevention Bureau at 874-8400 no later than Friday October 21, 2016 to schedule a full inspection of the property. If you fail to do so, the City may consider this a refusal to allow an inspection and seek an administrative inspection warrant in court. The City may also pursue its remedies for civil penalties for refusing to allow the inspection of the property.

Additionally, please see the attached Notice of Violation and Order to Correct from the City of Portland Fire Prevention Bureau for the violations that were noted on September 12. Please complete and return the form to the Fire Prevention Bureau by the date indicated. Your failure to do so may result in legal action, including the imposition of civil penalties.

Please contact the Fire Prevention Bureau at (207)874-8400 to schedule an inspection and resolve the outstanding violations. I look forward to your anticipated cooperation and appreciate your efforts to help keep the citizens of Portland safe.

Sincerely,

Anne M. Torregrossa

Associate Corporation Counsel

City of Portland

CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

October 11, 2016

Responsible Party 1:			
THIDWICK LLC			
100 COMMERCIAL ST			
PORTLAND, ME 04101			
Location	CBL	Inspection Date	
106 HIGH ST	039 A037001	9/12/2016	******
Inspector	Inspection Type	Status	
Donald Brown, Ii	FP Routine Inspection	Failed	

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must complete the proposed date of completion column by proposing a reasonable timeframe to remedy each violation. This form must be received by the Fire Prevention Bureau no later than 10/30/2016. The Bureau reserves the right to reject or modify any proposed plan of action, and may require evidence of sufficient financial and technical capacity to complete the proposed plan. Please contact the Bureau with any questions.

YOUR FAILURE TO SUBMIT A PLAN OF ACTION BY THE DATE PROVIDED, OR TO CORRECT ANY VIOLATION WITHIN THE APPLICABLE TIME FRAME, MAY RESULT IN LEGAL ACTION AGAINST YOU, THE IMPOSITION OF CIVIL PENALTIES, AND THE PURSUIT OF OTHER LEGAL REMEDIES.

Violation	Proposed Date of Completion
NFPA 101-7.9.3 EMERGENCY LIGHTS REQUIRE MAINTENANCE; 7.9.3 Periodic Testing of Emergency Equipment 7.9.3.1 Required emergency lighting systems shall be tested in accordance with one of the three options offered by 7.9.3.1.1, 7.9.3.1.2, or 7.9.3.1.3. 7.9.3.1.1 Testing of required emergency lighting systems shall be permitted to be conducted as follows: (1) Functional testing shall be conducted monthly with a minimum of 3 weeks and a maximum of 5 weeks between tests, for not less than 30 seconds, except as otherwise permitted by 7.9.3.1.1(2). (2) The test interval shall be permitted to be extended beyond 30 days with the approval of the authority having jurisdiction. (3) Functional testing shall be conducted annually for a minimum 1-1/2 hours if the emergency lighting system is battery powered. (4) The emergency lighting equipment shall be fully operational for the duration of the test required by 7.9.3.1.1(1) and (3). (5) Written records of visual inspections and tests shall be kept by the owner for inspection by the authority having jurisdiction. Emergency lighting does not work in the main restraunt area.	/
NFPA 101- 7.5.1.1 EXIT OBSTRUCTED ; Where exits are not immediately accessible from an open floor area, continuous passageways, aisles, or corridors leading directly to every exit shall be maintained and shall be arranged to provide access for each occupant to not less than two exits by separate ways of travel, unless otherwise provided in 7.5.1.1.3 and 7.5.1.1.4. Basement bulkhead exit is blocked with storage materials. Electrical panel and sprinkler system cotrol area blocked with storage materials.	IMMEDIATELY remove all obstructions from the exits. Your signature below indicates that all obstructions have been removed and will not be replaced.

Violation		Proposed Date of Completion
SERVICE ; Fire alarm system requires se of licensed master fire alarm companies www.portlandmaine.gov/fireprevention.	PTER 10 FIRE ALARM SYSTEM REQUIRES ervice by a licensed master fire alarm company. A list can be viewed at: ed and missing. We were only able to access the	//
VIOLATOR CERTIFICATION		
I agree to remedy the violations listed understand that I must contact the Fire entirely within the Bureau's discretion	within the timeframes provided. If I require addiction of the deadline of requention of the deadline of the deadline of the deadline to requent or deny.	tional time to comply, I st an extension, which i
I further understand that it is my resp have been remedied to do so. My fail violations have not been remedied.	onsibility to schedule a reinspection of my proper ure to schedule a reinspection shall be deemed an	ty once the violations admission that the
If I fail to comply with this agreement Portland Code of Ordinances §§ 1-15 action.	t, I understand that I am liable for penalties pursua and 10-25, and 30-A M.R.S. § 4452 and may be s	ant to the City of subject to further legal
Date	Responsible Party	
Date	Responsible Party	<u> </u>

Fire Prevention Bureau

SEEN AND AGREED

Date