CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager TAYLOR ELISE LOUISE ADAMS		Inspector Jason Duval	Inspection Date 2/15/2018	
Location	CBL	Status	Inspection Type	
5 NYE ST	044 A015001	Violations Exist	Inspection	

Code Int/Ext Floor Unit No. Area Compliance Date

1) 3.011

Violation: NFPA 101- 31.3.2.1.1 BOILER PROTECTION REQUIRED; THE AREAS DESCRIBED IN TABLE

31.3.2.1.1 SHALL BE PROTECTED AS INDICATED:

BOILER AND FUEL-FIRED HEATER ROOMS SERVING MORE THAN A SINGLE DWELLING UNIT

(MINIMUM SEPARATION/PROTECTION IS 1 HOUR OR SPRINKLERS)

Notes: Sprinkler required over heating systems.

2) 55.001

Violation: NFPA 101- 7.5.1.1.1 EXIT(S) OBSTRUCTED; Where exits are not immediately accessible from an

open floor area, continuous passageways, aisles, or corridors leading directly to every exit shall be maintained and shall be arranged to provide for each occupant to not less than two exits by separate

ways of travel, unless otherwise provided in 7.5.1.1.3 and 7.5.1.1.4.

Notes: Remove debris from all stairwells and underneath staircase in back.

3) 55.20

Violation: NFPA 101- 31.3.3.2 INTERIOR FINISH; INTERIOR WALL AND CEILING FINISH MATERIALS

COMPLYING WITH 10.2 SHALL BE PERMITTED AS FOLLOWS:

(1) EXIT ENCLOSURES- CLASS A OR B

(2) LOBBIES AND CORRIDORS- CLASS A OR B

(3) OTHER SPACES- CLASS A, B, OR C.

Notes: Non fire doors are required to be walled in and be appropriately fire rated or to be replaced by 1 hour

rated fire doors.

Comments: Field Inspection 2/15/18- Sprinkler head needed over boiler and water heaters and in basement.

Underneath back stairs required to be cleared. All stairwells need to be cleared of debris. Non-fire doors (2) in front staircase need to be 1-hour fire rated. (Walled in or fire door). Plan of action for the

non-fire doors due in 30 days.