
CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400



NOTICE OF VIOLATION AND ORDER TO CORRECT

November 16, 2017

Responsible Party 1: HIGHSTATE APTS INC 657 CONGRESS ST 1ST		
PORTLAND, ME 04101	PLOOK	
Location 45 STATE ST	CBL 044 B030001	Inspection Date
Inspector	Inspection Type	Status
Sean Donaghue	FP Routine Inspection	Failed

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 12/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation		Proposed Date of Completion
MARKED; 4.6.1 Residential units shall be of each residential unit shall be the floor de	ER 10 4.6.1, 4.6.2 UNIT/SUITE NUMBERS NOT designated using numerals. 4.6.2 The first numeral signation. are numbered with corresponding unit number	1/31/18
buildings or areas between which there are resistance rating, unless otherwise provider continuous to the finished grounded level. Holes in walls and ceiling noted throughout	JIRES MAINTENANCE; Fire barriers separating horizontal exits shall have a minimum 2-hour fire d in 7.2.4.4.1, and shall provide a separation that is , particularly 45 first floor main entry ceiling, 45 hall c. Please ensure proper fire rating is maintained	1/31/18
normally required to be kept closed shall no	BE SELF- OR AUTO-CLOSING; A door leaf of be secured in the open position at any time and accordance with 7.2.1.8.2, unless otherwise epair, maintenance or replacement.	Deve
NFPA 70 MISSING BOX COVERS; Refer to for missing box covers.	o NFPA 70, National Electrical Code, on standards sboxes noted without covers. All junctions boxes	1 /31//2

ion	Proposed Date of Completion
PA 101- 8.3.4.2 60 MINUTE FIRE DOOR REQUIRED; Refer to NFPA 101- Table 8.3.4.2 hat states fire door assemblies for vertical shafts (including stairways, exits, and refuse chutes) are rated and required for 1 hour. Basement access from both sides (45 and 47) require fire door installation	2/6/18
FINAL DATE OF COMPLETED VIOLATION(S)	2/4/18
FIRE PREVENTION BUREAU RE-INSPECTION OF COMPLETED VIOLATION(S)	2/8/18

The Bureau reserves the right to reject or modify any proposed plan of action, and may require evidence of sufficient financial and technical capacity to complete the proposed plan. Please contact the Bureau with any questions.

VIOLATOR CERTIFICATION

I agree to remedy the violations listed within the timeframes provided. If I require additional time to comply, I understand that I must contact the Fire Prevention Bureau <u>prior to the deadline</u> to request an extension, which is entirely within the Bureau's discretion to grant or deny.

I further understand that it is my responsibility to schedule a reinspection of my property once the violations have been remedied to do so. My failure to schedule a reinspection shall be deemed an admission that the violations have not been remedied.

If I fail to comply with this agree Portland Code of Ordinances §	ement, I understand that I am liable for penalties pursu § 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be s	ant to the City of subject to further legal
12 25 17 Date	Responsible Party	
Date	Responsible Party	*
SEEN AND AGREED Z Z / 1 7 Date	Fire Prevention Bureau	