389 Congress St.Rm 315 Portland, ME 04101 Phone: (207)874-8700 Fax: (207)874-8716

facsimile transmittal

	o: Chris Briley		From:		
Fax:	773-0194		Date:	January 2, 2003	
Phone:	775-6141		Pages: 1		
Re:	St. Dom's 044 H0	004			
□ Urger	nt □ For Revie	w 🗆 Please Com	ment	☑ Please Reply	☐ Please Recycle
	•	• •		•	•
	Code is r	nent on special inspector required for certain ele review prior to approv	ments of th		
	I have co	ompleted the initial rev	riew and ha	eve the following	questions/comments:
		The vertical shaft is re(710.3 BOCA).	equired to l	nave a 2-hour fire	separation assembly
	2)	What is the Fire rating of column detail 1 on page A-1-12? I assume fire dampers for the bathroom vents fire partition penetrations			
	4)	are omitted pursuant t Are there details or sp	o Section 7 becs that ac	14.1.5.2.1. ecompany the fire	
		language on the Floor			
				system is to be us	
	6)	What are the sound to assemblies? What is the access lac	ansmissio	ratings of all ter	