



North Face of Residence
Corner to be Repaired



North Face of Residence
Missing Fascia Board to be Replaced



West (Rear) Face of Residence
Gutter to be Installed along Roofline



West (Rear) Face of Residence
Siding to be Repaired / Replaced / Repainted