CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

	wner/Manag TEPHENS CL			1 -	Inspector John Bisesti			Inspection Date 04/11/2006	
Locatation CBL				Status	Status			Inspection Type	
198 SPRING ST 045 F026001			Re-Inspe	Re-Inspect 14 Days			Complaint-		
	Code	Int/Ext			Floor	Unit No.	Area	Compliance Date	
1)	6-108.4 Violation: Notes:	Exterior Stairways, st No hand rail.	tairwells, stairs, p	orches.	1	4	rear steps		
2)	6-108.1 Violation: Notes:	Exterior Various locations Foundations cellars, exterior walls, roofs Missing soffet vents/blocking				ations			
3)	6-108.1 Violation: Notes:	Exterior entire building Foundations cellars, exterior walls, roofs Missing siding and vapor barrier. Entire building. Not water tight, allowing moisture to penitrate interior of the building. Vilalated Articles 314, 312, and 310 of the Nation Electrical Code							
4)	6-108.3 Violation: Notes:	Exterior Exterior windows, doors and skylights Missing weather striping in various locations			ıs		Various locations		
5)	6-108.4 Violation: Notes:	Exterior Rear Deck Stairways, stairwells, stairs, porches. Missing guard rail and needs guard rail system to be braced securly as not to hinder egress. Missing ballasters in various locations					nder egress. Missing		
6)	6-108.3 Violation: Notes:		dows, doors and s		2	3	Various loc	ations	
7)	6-108.2 Violation: Notes:	Interior Interior floors Broken plaste	s, walls, ceilings a er, hanging	nd doors	2	3	Bedroom		
8)	6-108.2	Interior			2	3	Various loc	ations	

Various locations

Violation:

Violation:

Notes:

Notes:

9) 6-108.3

Interior floors, walls, ceilings and doors

Exterior windows, doors and skylights

Interior

Missing window screens.

Missing/unfinished drywall/plaster in various locations.

CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date 04/11/2006	
STEPHENS CLARK B		John Bisesti		
Locatation	CBL	Status	Inspection Type	
198 SPRING ST	045 F026001	Re-Inspect 14 Days	Complaint-	

Comments:

1st floor rear apt- No hand rail approx. 22.5 " to grade. No landing on exterior of door, no soffits insulation sticking out allowing rodents in to building, no siding allowing water to enter into exterior walls and wet romex, No weatherstriping on doors, windows not insul @ jambs 2nd floor rear apt. Exterior door does not seal, board nailed on angle near means of egress to brace railing, no ballusters along rails. One portion of deck missing guard rail, plaster falling down in one room, not finished in another room no screens on windows