Form # P 04

DISPLAY THIS CARD ON PRINCIPAL FRONTAGE OF WORK

CITY OF PORTLAND

Please Read Application And Notes, If Any, Attached

BU LE ME PARTIE TON

Permit Number: 100067

PERMIT ISSUED

This is to sortify that

This is to certify that ___STONE COAST PROPERTIES ** C /P & **

has permission to ____

Replace Plaster ceiling w/ gypsu wall boa

AT 603 CONGRESS ST

CB 046 D031001

FEB - 2 2010

provided that the person or persons, first or control on accepting this permit shall comply with all of the provisions of the Statutes of Make and of the construction, maintenance and use of buildings and structures, and of the application on file in this department.

Apply to Public Works for street line and grade if nature of work requires such information.

Notice tion of ispection must be given ind written termissic procured before this building or part hereof is lather for other particles. 24 HOU NOTICE IS REQUIRED.

A certificate of occupancy must be procured by owner before this building or part thereof is occupied.

OTHER REQUIRED APPROVALS

Fire Dept. CAPT. X. Sauties

Health Dept.

Appeal Board

Other _____

Department Name

Director - Building & Inspec

PENALTY FOR REMOVING THIS CARD

City of Portland, N	Aaine - Buil	ding or Use	Permi	t Application	n Permit No:	Issue Date	:	CBL:	
389 Congress Street,		v		• •	I			046 D0	31001
Location of Construction: Owner Name:				Owner Address:		<u> </u>		Phone:	
603 CONGRESS ST (STONE COAST PROPERTIES LL			142 HIGH ST STE 320					
Business Name:	Contractor Name: P & G Masonry Phone:			Contractor Address: P.O. Box 729 Old Orchard Permit Type:			Phone		
							2079348584		
Lessee/Buyer's Name								Zone:	
					Alterations - Co	mmercial			13-3
Past Use:		Proposed Use:			Permit Fee:	Permit Fee: Cost of Work:		CEO District:	
Commercial - Vacant Space		Commercial - Vacan		de Space -	\$1,020.00	/ \$100,00		2	
theohr.		Replace Plaster ceiling w/ gypsum			FIRE DEPT: Approved INSPEC				
		wall board			Use Use			Group: A- / Type: 3B	
					Denied Ost			IBC 2003	
					*See Condi	THAT		IBC 2	003
Proposed Project Description	on:					<u>ک</u> آ			<i>'</i>
Replace Plaster ceiling	w/ gypsum wa	ıll board			Signature: Signature:			7/64	
					PEDESTRIAN ACTIVITIES DISTRIC			T (P.A.D) d w/Conditions Denied	
					Treaton		proved in co		
_					Signature:		D	ate:	
Permit Taken By:	Date Ap	oplied For:			Zoning Approval				
Ldobson	01/22	2/2010							
This permit application does not prec Applicant(s) from meeting applicable Federal Rules.		preclude the	Spe	cial Zone or Revie	ews Zon	Zoning Appeal		Historic Preservation ソい Not in District or Landmark	
		able State and	☐ Sł	oreland	Variance				
2. Building permits do not include plumbing			☐ Wetland		Miscel	Miscellaneous		☐ Does Not Require Review	
septic or electrical work.									
3. Building permits are void if work is not started			☐ Flood Zone		Conditional Use			Requires Review	
within six (6) mon							Approved		
False information permit and stop all	a building Subdivision		bdivision	Interpretation		_ _			
permit and stop an	WOIK							1	(a. 1931
			Si	te Plan	Appro	ved		Approved w/	Conditions
		LICO						l D1	
PFRN	MT 155	UED	Maj Minor M		Denied			Denied	
PERMIT ISSUED			Oic	wicondula.				1/25/11	
	-n o ns	Λ .	Date:	125/10 MAN	Date:		Date	1/20	$\mu \sigma$
, , , F	EB - 2 20°	· -					K	$\langle \bigwedge$	lo. r
: _ ·		*,					15	. Hug	Drw,
С	ity of Portla	nd							C
	,								
			(ERTIFICATI	ON				
I hereby certify that I an	n the aumor of	record of the no				ic outhorized	l by the on	mer of reco	rd and that
I have been authorized b									
jurisdiction. In addition									
shall have the authority									
such permit.									
SIGNATURE OF APPLICANT			ADDRESS			DATE		PHONE	
and the state of t					-	2.112		1110	_
	_								
RESPONSIBLE PERSON IT	N CHARGE OF W	ORK, TITLE				DATE	;	PHO	NE

City of Portland, Maine - J	Building or Use Permit	ţ	refillt No:	Date Applied For:	CBL:
389 Congress Street, 04101 T	_		10-0067	01/22/2010	046 D031001
cation of Construction: Owner Name:			Owner Address:	Phone:	
603 CONGRESS ST (609)	STONE COAST PRO	STONE COAST PROPERTIES LL		142 HIGH ST STE 320	
Business Name:	Contractor Name:		Contractor Address:		Phone
	P & G Masonry		P.O. Box 729 Old Orchard		(207) 934-8584
Lessee/Buyer's Name	Phone:		Permit Type:	<u> </u>	
			Alterations - Comr	mercial	
Proposed Use:		Propos	ed Project Description:		<u> </u>
Commercial - theter (vacant) - Rewall board	eplace Plaster ceiling w/ gyps	sum Repla	ce Plaster ceiling w/	gypsum wall board	
•	s: Approved with Condition	s Reviewer	: Deborah Andrews	• •	
Note:					Ok to Issue:
-		lld the current c			ortion of the ate: 01/25/2010
Note:					Ok to Issue:
1) ANY exterior work requires District.	a separate review and approv	al thru Historic	Preservation. This p	roperty is located wi	thin an Historic
2) This permit is being approved work.	d on the basis of plans submi	tted. Any devia	ations shall require a	separate approval be	efore starting that
-	s: Approved with Condition	s Reviewer	: Tammy Munson	Approval Da	pr. =9
Note:					Ok to Issue:
1) This permit authorizes the re	placement of the ceiling only	. Any other wo	k requires separate p	ermits.	
2) Separate permits are required need to be submitted for appropriate to the submitted for approximately approxima	,	•	alarm or HVAC or e	xhaust systems. Sepa	arate plans may
3) Application approval based u and approrval prior to work.	ipon information provided by	/ applicant. Any	deviation from appr	oved plans requires	separate review
Dept: Fire Statu	s: Approved with Condition	s Reviewer	: Capt Keith Gautre	eau Approval Da	ate: 01/28/2010
Note:					Ok to Issue:
1) All construction shall comply	with NFPA 101				

PERMIT ISSUED

Comments:

2/2/2010-tmm: As discussed during our meeting, the ceiling is part of a historic building. There is historical significance with various features of the ceiling. In order to install a rated ceiling, these features would be removed. 3407. There is historical significance with various features of the ceiling. In order to install a rated ceiling, these features would be removed. 3407. There is historical significance with various features of the ceiling. In order to install a rated ceiling, these features would be removed. 3407. There is historical significance with various features of the ceiling is part of a historic building. There is historical significance with various features of the ceiling. In order to install a rated ceiling, these features would be removed. 3407. There is historical significance with various features of the ceiling. In order to install a rated ceiling, these features would be removed. 3407. There is historical significance with various features of the ceiling.

STATE THEATRE

General Building Permit Application

property within the City, payment arrangements must be made before permits of any kind are accepted.

Location/Address of Construction:	09 Congress Si	Trect
Total Square Footage of Proposed Structure/	Area Square Footage of Lot	Number of Stories
Tax Assessor's Chart, Block & Lot Chart# Block# Lot# 044 D03/ 00/	Applicant *must be owner, Lessee or Buyer Name Stone Const Prop LL Address 42 High St / Suite 3. City, State & Zip Parkand Manual O410)	772-1540
Lessee/DBA (If Applicable)	Owner (if different from Applicant) Name Address City, State & Zip	Cost Of Work: \$ // 000 C of O Fee: \$ // 000 Total Fee: \$ // 000
Address: 1.0.30+729 City, State & Zip OLI OR-Ch	If yes, please name If yes, please name YOUR GYPSUM WELL SONRY AND BRACH I	
Who should we contact when the permit is real Mailing address:	dy: 1 C 1 9 O 1 C 9 C 1	elephone: (102 027)
Please submit all of the information do so will result in the	outlined on the applicable Checklie automatic denial of your permit.	ist. Failure to
n order to be sure the City fully understands the nay request additional information prior to the isshis form and other applications visit the Inspection office, room 315 City Hall or call 874-8703.	suance of a permit. For further information of	or to download copies of
hereby certify that I am the Owner of record of the nat I have been authorized by the owner to make this ws of this jurisdiction. In addition, if a permit for worthorized representative shall have the authority to entrovisions of the codes applicable to this permit.	application as his/her authorized agent. I agree trk described in this application is issued, I certify	to conform to all applicable that the Code Official's
ignature:	Date: //22/11)	2 2 2010
This is not a permit; you may	not commence ANY work until the person	it is issue; ding laggestions
(/	pepe	Pottland Maine

Revised 9-26-08



75 York Street
Portland, Maine 04101
phone 207 772 4656
fax 207 828 4656
www.simonsarchitects.com

MEMORANDUM

date:

01/21/2010

project:

STATE THEATER CEILING: 2009-0160

to:

Richard McCarthy

Office of State Fire Marshall 52 State House Station Augusta, ME 04333-0052

phone:

fax:

(207) 626-3886 (207) 624-8968

subject:

Ceiling Replacement

In the past two years major improvements have been made to the State Theater in Portland in preparation for its future reopening. Fire escapes have been redesigned and replaced. Electrical wiring has been upgraded to current code. Fire alarms, exit lights and emergency lighting have been improved to meet code. Exit doors and egress hardware have been replaced. Men's restrooms have been relocated from the basement to the main entry level.

The major outstanding issue is the existing plaster ceiling. It has been damaged from past roof leaks and physical abuse from people walking on top of the suspended structure. There are documented incidences of plaster falling and evidence of several patches over the years. After close visual inspection of both the top and underside, it has been determined the only solution is to remove the plaster and replace the ceiling. Several options were reviewed and installing gypsum wall board (GWB) is the most reasonable solution.

L&L Structural Engineering has reviewed the existing metal supports and hanger structure. The proposal removes the existing heavy plaster, which averages 14lb/sf. New light gauge metal furring will be installed and 2 layers of ¼" GWB will be formed around the shallow barrel vaults. The GWB system is relatively light in weight but the structural system is designed for additional loading if mass needs to be added to adjust acoustical performance in the future.

Philip R. Sherman, P.E. has also reviewed the project in regards to fire and building codes. His review suggest it is reasonable not to fire rate the replacement ceiling as the existing ceiling is not fire rated. We presented this argument to the local building and fire departments along with the state fire inspector. There were some questions and concerns, especially with the volume of the space above the ceiling. It was agreed heat detectors could easily be added in this space to provide an added sense of security. They were all open to considering the proposal with more information and a formal application.

project:

State Theater Ceiling

2009-0160-CoilingLouer.doc

date: 01/21/2010

Attached with this memo is the following information:

Application for Construction Permit \$150 check for application fee
Floor plan showing extent of ceiling area (SSA)
Structural code summary (L&L)
Section details of ceiling replacement connections (L&L)
Narrative code summary (Phil Sherman)

project: Foxcroft Academy Residences date: 1/21/10

GENERAL NOTES:

- 1. The notes on the drawings are not intended to replace specifications. in addition to general notes. See specifications for requirements
- 2. Structural drawings shall be used in conjunction with job specifications and architectural, mechanical, electrical, plumbing, and site drawings. Consult, openings, chases, inserts, reglets, sleeves, depressions, and other details not shown on structural drawings.
- 3. All dimensions and conditions must be verified in the field. Any discrepancies shall be brought to the attention of the engineer before proceeding with the affected part of the work.
- 4. Do not scale plans.
- 5. Sections and details shown on any structural drawings shall be considered typical for similar conditions.
- 6. All propietary products shall be installed in accordance with the manufacturers written instructions.
- 7. The structure is designed to be self supporting and stable after the erection is complete. It is the contractor's sole responsibility to determine erection procedures and sequencing to ensure the safety of the building and its components during erection. This includes the addition of necessary shoring, sheeting temporary bracing, guys or tiedowns. Such material shall remain the property of the contractor after completion of the project.
- 8. All applicable federal, state, and municipal regulations shall be followed, including the federal department of labor occupational safety and health act.

DESIGN LOADS:

- 1. Building code: IBC (2003) International Building Code.
- 2. Design Dead Loads:

...... 10 psf (4 psf for drywall shown + 6 psf potential Ceilina future weight for acoustical dampening).

3. Seismic and Internal Pressure Design per IBC 2003.

STRUCTURAL STEEL NOTES:

1. Structural steel fabrication, erection, and connection design shall conform to AISC "Specification for the design, fabrication, and erection of structural steel"—Ninth edition

RECEIVED

JAN 22 2010

- 2. Structural steel:
 - a) Structural steel shall conform to ASTM A-36.
 - b) Structural tubing shall conform to ASTM A-500 GR-B
 - c) Structural pipe shall conform to ASTM A-53, TYPE E OR S

3. All welding shall conform to AWS D1.1-Latest edition. Welding electrodes shall be E70XDept. of Building InspectionS City of Portland Maine

LIGHT GAGE METAL FRAMING:


- 1. Acceptable light gage Manufacturer: Dietrich, Marino, or approved equal.
- 2. The extent of the work for the lightgauge framing system is detailed on the drawings. These notes shall be worked in conjunction with those drawings and the specifications.
- 3. The following specifications and publications shall be followed.
 - a) American iron and steel institute cold form design manual, specification for the design of cold form steel structural members - latest edition.
 - b) American society for testing and materials (ASTM).
 - c) American institute of steel construction Manual of Steel Construction 9TH Edition.
- 4. Fabrication of light gage steel shall conform with requirements of ASTM A446 with the following minimum yield points (Fy):
 - a) 16 gage. and heavier Fy = 50,000 psi (Grade D)


 - b) 18 gage. Fy = 33,000 Psi (Grade A) c) 20 gage. Fy = 33,000 PSI (Grade A)
- 5. Manufacturer of studs, runners, tracks and other framing members shall comply with ASTM C955.
- 6. Framing components and accessories shall be galvanized per ASTM A525 minimum G60 coating.
- 7. Screws and other attachment devices shall have a protective coating equivalent to cadmium or zinc plating and shall comply with ASTM A165 Type NS. self tapping screws shall be of the minimum diameter as indicated on the design drawings for each specific attachment detail. Penetration through joined materials shall not be less than three exposed threads.



29135

designed by: JHL STATE THEATRE L & L STRUCTURAL drawn by: ENGINEERING SERVICES, INC. **AKB** 609 CONGRESS STREET SIX Q STREET checked by: SOUTH PORTLAND, MAINE PORTLAND, MAINE JHL PHONE: (207) 767-4830 FAX: (207) 799-5432 scale: NONE date: 1-20-10 **GENERAL NOTES S1**





PHILIP R. SHERMAN, P.E.

FIRE PROTECTION ENGINEERING AND BUILDING CODE CONSULTING

P.O. BOX 216
444 WILMOT CENTER ROAD
ELKINS, NH 03233-0216
PHONE: 603-526-6190
FAX: 603-526-4979

EMAIL: PSHERMAN@PRSHERMAN.COM

Date: January 16, 2010

Proj: 1413.01

Scott Simons Architects 75 York Street Portland, ME 04101

Attention: Mr. Stephen Fraser

Re: State Theater

Portland, Maine

Requirement for Fire Rated Ceiling

Dear Mr. Fraser:

Based on a site visit on December 17, 2009, here is my analysis of the requirement for fire rating of the proposed replacement ceiling in the house.

- 1. The building is a six story mixed occupancy building, including at least Group A1, B and M. The building is fully sprinklered.
- 2. The current roof steel is unprotected, and the current ceiling is not designed to be fire rated. Aside from the fire rating of the plaster ceiling, there are air grills and duct openings in the ceiling, and possibly other openings, that are not fire rated. The remainder of the building appears to have been constructed of fire rated construction to some unknown level. Columns, beams and the other roofs are of steel protected by "pyrobar", which appears to be gypsum blocks, floor and roof decks are concrete. No attempt to assess the level of fire rating was made.
- 3. 2003 IBC 102.6 indicates that "The legal occupancy of any structure... may continue without change except...as deemed necessary by the building official for the general safety and welfare of the occupants and the public."
 - a. The Portland City Code amends this as follows: Section 102.6 Existing structures, is amended by deleting the words "the International Property Maintenance Code or the International Fire Code" and adding the words "the Minimum Standards for Housing

and the NFPA Code as adopted by the City of Portland."; and by adding the words "and/or the Fire Chief" after the words "building official."

- 4. 2003 IBC 3403.1 requires alterations to conform with the requirements for new construction.
- 5. Per Chapter 5, the minimum construction type that would be required if the building were new is Type IIA, for the six story Group B. Depending on the area of the building, Type IB might be required.
- 6. Per Table 601, with note c1, and assuming that there are rated walls between the Group M and the Group A space, the roof would not need to be rated if every part of the roof construction is more than 20 feet above the floor immediately below. This is the case in the auditorium, except near the back of the balcony and in the light booth..
- 7. In terms of the building code, this then gives the building inspector some latitude.
 - a. A strict reading of the code would require the entire replacement portion of the ceiling to be one hour rated (one hour for Type IIA or IB). If the mural at the front is to remain, this means the expense of rating the ceiling, which the remaining portion is not effectively rated, with no requirement that it be upgraded. In lieu of this, the roof trusses could be sprayed or otherwise protected.
 - b. The building authorities might also be convinced that the portion of the roof structure which is within 20 feet of the (balcony) floor, is small, the fuel load is small (seating and incidental) and the area is sprinklered.
- 8. The occupant load of the house is slightly less than 1500 persons. Of this, about 550 seats are located at the balcony. 2006 NFPA 101 13.1.6, as it applies to existing buildings, requires Type II(111) construction, which equates to IBC Type IIA, with the same exception for roof structure more than 20 feet off the floor.
- 9. This means that the building as it sits does not comply with NFPA 101, as it applies to existing buildings. The ceiling, including the portion not being reworked, is therefore required to be one hour rated, or the roof structure needs to be otherwise protected. Again, an appeal based on the limited extent of the problem, the relatively low fuel load, and automatic sprinklers might be considered.

Based on the above information, I propose that the replacement ceiling not be required to be fire rated, due to the following:

• The concealed space above the ceiling does not require sprinklers, per 2002 NFPA 13 8.14.1.2.2. This section does not require sprinklers in noncombustible and limited combustible concealed spaces with limited access and not permitting occupancy or storage of combustibles, even if openings as for a plenum are provided.

- The only combustibles above the ceiling are plank catwalks. These will be sprayed with an intumescent finish to provide a Class A flame spread rating.
- Heat detection connected to the building fire alarm will be provided above the ceiling. The
 details of the spacing of these detectors will be agreed with the local building and fire
 authorities.
- According to the architect, the replacement ceiling reduces the live load of the ceiling from an average of about 14 lbs/sf to about 3 lbs/sf. The city will not require changes to the roof structure as the existing live load is being reduced.

Please review these issues and let me know if further information is required.

Yours truly:

Philip R. Sherman, P.E.

C:\(MaProj\)[413\][413001.wpd