## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

July 12, 2017

Responsible Party 1:				
Holt Anthony				
PO BOX 3614				
PORTLAND, ME 04104				
Location	CBL	Inspection Date		
Location 35 DEERING ST	<b>CBL</b> 047 B022001	<b>Inspection Date</b> 6/19/2017		
		-		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 7/30/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
<b>NFPA 101- 7.5.1.1 EXIT OBSTRUCTED</b> ; Where exits are not immediately accessible from an open floor area, continuous passageways, aisles, or corridors leading directly to every exit shall be maintained and shall be arranged to provide access for each occupant to not less than two exits by separate ways of travel, unless otherwise provided in 7.5.1.1.3 and 7.5.1.1.4. Rear exit completely blocked with debris.	IMMEDIATELY remove all obstructions from the exits. Your signature below indicates that all obstructions have been removed and will not be replaced.
NFPA 101- 7.2.1.8.1 FIRE DOORS MUST BE SELF- OR AUTO-CLOSING; A door leaf normally required to be kept closed shall not be secured in the open position at any time and shall be self-closing or automatic-closing in accordance with 7.2.1.8.2, unless otherwise permitted by 7.2.1.8.3.  Apt. entry doors require closers.	//
NFPA 720- 5.5.6.1 CO ALARMS REQUIRED; The performance, location, and mounting of notification appliances used to initiate or direct action, evacuation or relocation of the occupants, or for providing information to occupants or staff, shall comply with the requirements of Chapter 6.  Apt. #3 third floor, has no CO detector.	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
NFPA 101- 31.3.4.5.1 SMOKE ALARMS REQUIRED; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements.  Apt. #2 second floor bedroom smoke detector has been removed.	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.

Violation		Proposed Date of Completion
31.3.2.1.1 shall be protected as inc than a single dwelling unit (minimu	OTECTION REQUIRED; The areas described in Table licated: Boiler and fuel-fired heater rooms serving more m separation/protection is 1 hour or sprinklers) basement require sprinkler protection.	//
		//_
FINAL DATE OF COMPLETED V	IOLATION(S)	//
FIRE PREVENTION BUREAU RE	-INSPECTION OF COMPLETED VIOLATION(S)	//
	reject or modify any proposed plan of action, and may capacity to complete the proposed plan. Please contact	-
	listed within the timeframes provided. If I require add he Fire Prevention Bureau <u>prior to the deadline</u> to requ iscretion to grant or deny.	
· ·	y responsibility to schedule a reinspection of my prope ly failure to schedule a reinspection shall be deemed an ed.	•
	ement, I understand that I am liable for penalties pursus $31-15$ and $10-25$ , and $30-A$ M.R.S. $34452$ and may be $34452$ and $34452$ and $34452$ and $3452$ and	• •
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	