CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

June 6, 2017

Responsible Party 1:		
Property Management Group		
PO Box 10991		
Portland, ME 04104		
Location	CBL	Inspection Date
84 PARK AVE	048 B005001	5/19/2017
Inspector	Inspection Type	Status
Edward Doughty	FP Routine Inspection	

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 6/30/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 1- 19.1.2 INSIDE STORAGE NOT ORDERLY; Persons owning or having control of any property shall not allow any combustible waste material to accumulate in any area or in any manner that creates a fire hazard to life or property. Air Conditioners (2) on top of the Amore on the second floor Stairway. Air Conditioners are an accelerant for the spread of fire. The location of the Air Conditioners (on the top of the Amore) are a hazard for falling on a Firefighter during a fire emergency and causing severe injury.	
NFPA 101- 7.5.1.1.1 EXIT(S) OBSTRUCTED; Where exits are not immediately accessible from an open floor area, continuous passageways, aisles, or corridors leading directly to every exit shall be maintained and shall be arranged to provide for each occupant to not less than two exits by separate ways of travel, unless otherwise provided in 7.5.1.1.3 and 7.5.1.1.4. rear Stairway / Second Floor has an accumulation of materials that are an abstruction for Tenants and Firefighters in a hazardous Fire condition	
NFPA 70 JUNCTION BOXES REQUIRE COVERS; Refer to NFPA 70, National Electrical Code, on standards regarding junction boxes requiring covers. Junction Boxes (few) in the basement need covers. They were pointed out to the Management Official.	
NPFA 101- 31.3.4.5.1 SMOKE DETECTOR VIOLATION; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms on all levels of the dwelling unit, including basements. Smoke / CO Detector in the Hallway of Apartment 05 was not properly installed. Detector was not seated in the base appropriately	

Violation		Proposed Date of Completion
FINAL DATE OF COMPLETED	VIOLATION(S)	//
FIRE PREVENTION BUREAU	RE-INSPECTION OF COMPLETED VIOLATION(S)	//
•	to reject or modify any proposed plan of action, and may cal capacity to complete the proposed plan. Please contaction	-
•	ns listed within the timeframes provided. If I require add t the Fire Prevention Bureau <u>prior to the deadline</u> to req s discretion to grant or deny.	1 2
	my responsibility to schedule a reinspection of my prope My failure to schedule a reinspection shall be deemed a died.	
	reement, I understand that I am liable for penalties pursi §§ 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	