CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

August 22, 2017

Responsible Party 1:				
Woitasek Steven W.				
57 GRANT ST				
PORTLAND, ME 04101				
Location	CBL	Inspection Date		
Location 57 GRANT ST	CBL 048 B017001	Inspection Date 3/21/2017		
		-		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 9/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101- 31.3.7 FLOOR/ CEILINGS ASSEMBLY NOT SMOKE-TIGHT ; In buildings other than those meeting the requirements of 31.3.7.1, 31.3.7.2, 31.3.7.3, 31.3.7.4, or 31.3.7.5, in addition to the following criteria to be met.	//
Holes in walls and celing in basement stairwell. Hole in wall, rear stairwell. Hole in wall front stairwell, 3rd floor.	
NFPA 101- 7.2.1.8.1 FIRE DOORS MUST BE SELF- OR AUTO-CLOSING; A door leaf normally required to be kept closed shall not be secured in the open position at any time and shall be self-closing or automatic-closing in accordance with 7.2.1.8.2, unless otherwise permitted by 7.2.1.8.3.	//
Fire doors not self closing throughout	
NFPA 101- 7.1.8 STAIR GAURDS MUST BE REPAIRED; Guards in accordance with 7.2.2.4 shall be provided at the open sides of means of egress that exceed 30 inches above the floor or the finished ground level below. Ballisters need repair in front hall	//
NFPA 101- 31.3.3.2 INTERIOR FINISH; Interior wall and ceiling finish materials complying with 10.2 shall be permitted as follows: (1) Exit enclosures- Class A or B (2) Lobbies and corridors- Class A or B (3) Other Spaces- Class A, B, or C. Paneling in rear hall	//
NFPA 70- ARTICLE 110 B CERTIFY ELECTRICAL SYSTEM; Listed or labeled equipment shall be installed and used in accordance with any instructions included in the listing or labeling. Entire electrical system needs to be looked at. Outside meters not secured to the building	//

Violation		Proposed Date of Completion
NFPA 70 MISSING COVER ON F requirements of missing cover on Electrical panel at front of baseme	·	//
NFPA 70 MISSING BREAKER IN information on missing breakers in Blank required in 3rd floor sub-part	·	//_
FINAL DATE OF COMPLETED \	/IOLATION(S)	//_
FIRE PREVENTION BUREAU RI	E-INSPECTION OF COMPLETED VIOLATION(S)	//
	o reject or modify any proposed plan of action, and may all capacity to complete the proposed plan. Please contaction.	=
•	s listed within the timeframes provided. If I require add the Fire Prevention Bureau <u>prior to the deadline</u> to req discretion to grant or deny.	- ·
· ·	ny responsibility to schedule a reinspection of my propo Ny failure to schedule a reinspection shall be deemed a ied.	•
	gement, I understand that I am liable for penalties pursing \S 1-15 and 10-25, and 30-A M.R.S. \S 4452 and may be	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	