DISPLAY THIS CARD ON PRINCIPAL FRONTAGE OF WORK

CITY OF PORTLAND

BUILDING PERMIT





This is to certify that <u>MICHAEL SCANNELL</u> Job ID: <u>2012-10-5121-ALTCOMM</u> Located At <u>264 STATE ST</u>

CBL: 048- D-023-001

Dames

has permission to EMERGENCY structural fire escape repair-

provided that the person or persons, firm or corporation accepting this permit shall comply with all of the provisions of the Statues of Maine and of the Ordinances of the City of Portland regulating the construction, maintenance and use of the buildings and structures, and of the application on file in the department.

Notification of inspection and written permission procured before this building or part thereof is lathed or otherwise closed-in. 48 HOUR NOTICE IS REQUIRED. A final inspection must be completed by owner before this building or part thereof is occupied. If a certificate of occupancy is required, it must be

Fire Prevention Officer

Code Enforcement Officer / Plan Reviewer

THIS CARD MUST BE POSTED ON THE STREET SIDE OF THE PROPERTY PENALTY FOR REMOVING THIS CARD

BUILDING PERMIT INSPECTION PROCEDURES Please call 874-8703 or 874-8693 (ONLY) or email: buildinginspections@portlandmaine.gov

With the issuance of this permit, the owner, builder or their designee is required to provide adequate notice to the city of Portland Inspections Services for the following inspections. Appointments must be requested 48 to 72 hours in advance of the required inspection. The inspection date will need to be confirmed by this office.

- Please read the conditions of approval that is attached to this permit!! Contact this office if you have any questions.
- Permits expire in 6 months. If the project is not started or ceases for 6 months.
- If the inspection requirements are not followed as stated below additional fees may be incurred due to the issuance of a "Stop Work Order" and subsequent release to continue.

Final Inspection

The project cannot move to the next phase prior to the required inspection and approval to continue, REGARDLESS OF THE NOTICE OF CIRCUMSTANCES.

IF THE PERMIT REQUIRES A CERTIFICATE OF OCCUPANCY, IT MUST BE PAID FOR AND ISSUED TO THE OWNER OR DESIGNEE BEFORE THE SPACE MAY BE OCCUPIED.



Strengthening a Remarkable City, Building a Community for Life . www.portlandmaine.gov

Director of Planning and Urban Development Jeff Levine

Job ID: 2012-10-5121-ALTCOMM

Located At: 264 STATE ST

CBL: 048- D-023-001

Conditions of Approval:

Zoning

- 1. This permit is being approved on the basis of plans submitted. Any deviations shall require a separate approval before starting that work.
- Separate permits shall be required for future changes or additions to any of the exterior means of egress.
- 3. This property shall remain thirteen residential dwelling units. Any change of use shall require a separate permit application for review and approval.
- ANY exterior work requires a separate review and approval thru Historic Preservation. This
 property is located within an Historic District.

Historic

1. Work to result in no expansion of fire escape's footprint.

Building

1. This permit is approved based on the evaluation of the existing fire escape by an engineer with Fire Escape Inspection Services, INC. The repairs shall be visually inspected and approved by the professional engineer.

Fire

- 1. Permit is to completely refurbish fire escape as currently configured under direct engineer oversight in lieu of load testing.
- 2. All work shall comply with the City of Portland Fire Department Rules and Regulations, Chapter 9. <u>http://www.portlandmaine.gov/fireprevention/fdrulesandregulations.pdf</u>
- 3. Full painting shall not occur until all repairs are inspected and certified under engineer oversight.

City of Portland, Maine - Building or Use Permit Application

389 Congress Street, 04101 Tel: (207) 874-8703, FAX: (207) 8716

| Job No: 2012-10-5121-ALTCOMM | Date Applied: 10/4/2012 | | CBL: 048- D-023-001 | | | | |
|--|---|---|--|---|---|--|--|
| Location of Construction: 264 STATE ST | Owner Name: MICHAEL SCANNELL | | Owner Address: PO BOX 9715-747 PORTLAND, MAIN | NE 04104 | | Phone: 400-6725 | |
| Business Name: | Contractor Name: FIRE ESCAPE SER | VICES | Contractor Addre 19 WESLEY PAR 02143 | ess: K SOMERVILLE ! | MASSACHUSETTS | Phone: (617) 378-2287 | |
| Lessee/Buyer's Name: | Phone: | | Permit Type: BLDG | | | Zone: R-6 | |
| Past Use: Thirteen Residential Dwelling Units | Proposed Use: Same: Thirteen Resi Dwelling units – To o maintenance of an ex escape in the existing | do xisting fire | Cost of Work: \$15,000.00 Fire Dept: lo(25)l2 | Approved La Denied N/A |) conditions | CEO District: Inspection: Use Group: R-2- Type: N/A | |
| Proposed Project Description EMERGENCY fire escape structu | - no new expansions | | Signature: Bla | · ^ / | 53) D.) | Mubec'og signature: JMB W/25/12 | |
| Permit Taken By: Brad | | | L | Zoning Appro | oval | 49,480,000 to 100000 const of 10000 | |
| This permit application does not preclude the Applicant(s) from meeting applicable State and Federal Rules. Building Permits do not include plumbing, septic or electrial work. Building permits are void if work is not started within six (6) months of the date of issuance. False informatin may invalidate a building permit and stop all work. | | Special Zone or Reviews Shoreland Wetlands Flood Zone Subdivision Site Plan Maj _Min _MM Date: 0 W. M.CONDU io/10/11 CERTIFICATION | | Zoning Appeal Variance Miscellaneous Conditional Use Interpretation Approved Denied S Date: | Not in Di Does not Requires Approved | 10/07/17 | |

I hereby certify that I am the owner of record of the named property, or that the proposed work is authorized by the owner of record and that I have been authorized by the owner to make this application as his authorized agent and I agree to conform to all applicable laws of this jurisdiction. In addition, if a permit for work described in the application is issued, I certify that the code official's authorized representative shall have the authority to enter all areas covered by such permit at any reasonable hour to enforce the provision of the code(s) applicable to such permit.

| SIGNATURE OF APPLICANT | ADDRESS | DATE | PHONE |
|------------------------------|----------------|------|-------|
| | | | |
| RESPONSIBLE PERSON IN CHARGE | OF WORK, TITLE | DATE | PHONE |

| | | L) ilding Permit Applic | | | | |
|-------|---|---|----------------------------|--|--|--|
| OF PO | St you or the property owner owes real estate or personal property taxes or user charges on any property within the City, payment arrangements must be made before permits of any kind are accepted. H $20/2 - 10 - 5/2 - AHCMM$ | | | | | |
| | Location/Address of Construction: 264 | | K-Listric | | | |
| | Total Square Footage of Proposed Structure/Area Square Footage of Lot | | | | | |
| | Tax Assessor's Chart, Block & Lot Chart# Block# Lot# | Applicant * must be owner, Lessee or Buyer Name Michael Scannell | 207-400-6725 | | | |
| | 048 2023 | Address BBOX 9715-747 City, State & Zip Portland Me 041 | | | | |
| | Lessee/DBA (If Applicable) | Owner (if different from Applicant) Name | Cost Of Work: \$ 15,000 | | | |
| | OCT 04 2012 | Address | C of O Fee: \$ | | | |
| | Dept of Building Inspections Dept of Portland Mainte | City, State & Zip | Total Fee: \$ | | | |
| | Current legal use (i.e. single family) If vacant, what was the previous use? Proposed Specific use: Is property part of a subdivision? | | 13 residential D.Y | | | |
| 7 | Project description: Maintenance of existing structural then scrape + paint Structures then scrape + paint Contractor's name: Frie Fscape Service Address: 19 Wesley PK. | | | | | |
| - | | | | | | |
| | City, State & Zip_ <u>Somerville</u> <u>MG</u> <u>GATT-378-2287</u> Telephone: Who should we contact when the permit is ready: <u>Francisce Meneses</u> Telephone: | | | | | |
| | Mailing address: <u>Same</u> . | | | | | |

Please submit all of the information outlined on the applicable Checklist. Failure to do so will result in the automatic denial of your permit.

In order to be sure the City fully understands the full scope of the project, the Planning and Development Department may request additional information prior to the issuance of a permit. For further information or to download copies of this form and other applications visit the Inspections Division on-line at <u>www.portlandmaine.gov</u>, or stop by the Inspections Division office, room 315 City Hall or call 874-8703.

I hereby certify that I am the Owner of record of the named property, or that the owner of record authorizes the proposed work and that I have been authorized by the owner to make this application as his/her authorized agent. I agree to conform to all applicable laws of this jurisdiction. In addition, if a permit for work described in this application is issued, I certify that the Code Official's authorized representative shall have the authority to enter all areas covered by this permit at any reasonable hour to enforce the provisions of the codes applicable to this permit.

Date: Signature permit; you may not commence ANY work until the permit is issue is is not a



Strengthening a Remarkable City, Building a Community for Life . www.portlandmaine.gov

Receipts Details:

Tender Information: Check, Check Number: 838008 Tender Amount: 170.00

Receipt Header:

Cashier Id: bsaucier Receipt Date: 10/4/2012 Receipt Number: 48960

Receipt Details:

| Referance ID: | 8265 | Fee Type: | BP-Constr | | |
|--|---------------------|-----------|-----------|--|--|
| Receipt Number: | 0 | Payment | | | |
| | | Date: | | | |
| Transaction | 170.00 | Charge | 170.00 | | |
| Amount: | | Amount: | | | |
| Job ID: Job ID: 2012-10-5121-ALTCOMM - EMERGENCY fire escape structure | | | | | |
| Additional Comm | ents: 264 State St. | | | | |

Thank You for your Payment!



FIRE ESCAPE ENGINE 264 State St Portland ME 04101

Portland ME

P1

PHOTOS OF YOUR FIRE ESCAPE INSPECTION

254 CASE NUMBE

The overall condition of this fire escape system is poor due to deterioration caused by lack of structural and paint maintenance. Most fire escape systems are 50 to 75 years old and have had structural repairs to all the major structural connections done at least once. Square head bolts are replaced by hexagonal head bolts on stringers, treads, supports, rails and cantilevers/ladders because square bolts cause the most injuries when they fail. By law, all square head bolts must be replaced by hex head bolts. This fire escape system has multiple connection failures due to internal rust growth. The support connections to the building wall cement or thru-bolt - are unverified and require internal and/or external verification by vendor during repairs/refurbishment. Cantilever/ladder systems must be balanced when released and drop 2 to 3 feet per second.



opyright 2012 This report and attached documents are for the express purpose of summary notification to appropriate fire department, housing or code enforcement officials and cannot be used by or for private or mmercial purposes unless permission is given in writing by fire escape inspectional services inc. Full reports must be submitted attached to this report and on testing agency's letterhead.




all of Maine

FIRE ESCAPE ENGINEERS 264 State St Portland ME 04101

PHOTOS OF YOUR FIRE ESCAPE INSPECTION

254 Case Numbe

The overall condition of this fire escape system is poor due to deterioration caused by lack of structural and paint maintenance. Most fire escape systems are 50 to 75 years old and have had structural repairs to all the major structural connections done at least once. Square head bolts are replaced by hexagonal head bolts on stringers, treads, supports, rails and cantilevers/ladders because square bolts cause the most injuries when they fail. By law, all square head bolts must be replaced by hex head bolts. This fire escape system has multiple connection failures due to internal rust growth. The support connections to the building wall - cement or thru-bolt - are unverified and require internal and/or external verification by vendor during repairs/refurbishment. Cantilever/ladder systems must be balanced when released and drop 2 to 3 feet per second.



Copyright 2012 This report and attached documents are for the express purpose of summary notification to appropriate fire department, housing or code enforcement officials and cannot be used by or for private or commercial purposes unless permission is given in writing by fire escape inspectional services inc. Full reports must be submitted attached to this report and on testing agency's letterhead.




FIRE ESCAPE ENGINEERS 264 State St Portland ME 04101

PHOTOS OF YOUR FIRE ESCAPE INSPECTION

254 Case Numbe

The overall condition of this fire escape system is poor due to deterioration caused by lack of structural and paint maintenance. Most fire escape systems are 50 to 75 years old and have had structural repairs to all the major structural connections done at least once. Square head bolts are replaced by hexagonal head bolts on stringers, treads, supports, rails and cantilevers/ladders because square bolts cause the most injuries when they fail. By law, all square head bolts must be replaced by hex head bolts. This fire escape system has multiple connection failures due to internal rust growth. The support connections to the building wall - cement or thru-bolt - are unverified and require internal and/or external verification by vendor during repairs/refurbishment. Cantilever/ladder systems must be balanced when released and drop 2 to 3 feet per second.



COPYRIGHT 2012 THIS REPORT AND ATTACHED DOCUMENTS ARE FOR THE EXPRESS PURPOSE OF SUMMARY NOTIFICATION TO APPROPRIATE FIRE DEPARTMENT, HOUSING OR CODE ENFORCEMENT OFFICIALS AND CANNOT BE USED BY OR FOR PRIVATE OR DOMERCIAL PURPOSES UNLESS PERMISSION IS GIVEN IN WRITING BY FIRE ESCAPE INSPECTIONAL SERVICES INC. FULL REPORTS MUST BE SUBMITTED ATTACHED TO THIS REPORT AND ON TESTING AGENCY'S LETTERHEAD.




FIRE ESCAPE ENGINEERS 264 State St Portland ME 04101

254 Case Numbe

Portland ME

PHOTOS OF YOUR FIRE ESCAPE INSPECTION

The overall condition of this fire escape system is poor due to deterioration caused by lack of structural and paint maintenance. Most fire escape systems are 50 to 75 years old and have had structural repairs to all the major structural connections done at least once. Square head bolts are replaced by hexagonal head bolts on stringers, treads, supports, rails and cantilevers/ladders because square bolts cause the most injuries when they fail. By law, all square head bolts must be replaced by hex head bolts. This fire escape system has multiple connection failures due to internal rust growth. The support connections to the building wall - cement or thru-bolt - are unverified and require internal and/or external verification by vendor during repairs/refurbishment. Cantilever/ladder systems must be balanced when released and drop 2 to 3 feet per second.



ppyright 2012 This report and attached documents are for the express purpose of summary notification to appropriate fire department, housing or code enforcement officials and cannot be used by or for private or mmercial purposes unless permission is given in writing by fire escape inspectional services inc. Full reports must be submitted attached to this report and on testing agency's letterhead.

