

## CODE CASE DETAILED REPORT RR1800063 FOR CITY OF PORTLAND

Case Type: Long Term Residential   Status: Inspection Scheduled		•		Opened Date:	04/23/2018	
		cheduled	District: N/A		Closed Date:	NOT CLOSED
Assigned To:	Admin Fire		Desc	ription:		
arcel: 053 A015001 Main		Address: 23 Boynton St Main Portland, ME				
Emergency Cont	act	Proper	ty Manager	Owner		
Margaret Broussard		Neil Stillman		John Wierszchalek		
Portland, ME 04101 Mobile: 9786211237		97A Exchange St Portland, ME 04102 Mobile: 2077738169		22 Fayette St #3 Beverly, MA 01915 Mobile: 9786211001		
Inspection Number		Inspection Type		Inspection Date	Inspection Sta	tus
Code Case		Code Description		Code Comments	Deadline Date	Resolved Date
001234-2018		FP Routine Fire Inspection		4/23/2018	In Violation	
NFPA 101-31.3.4.5; City Code 10-3(i)		Photoelectric, hardwired with battery backup smoke alarms must be provided in every sleeping room, outside every sleeping area, and on every level, including the basement.		IMMEDIATELY install temporary alarms wher required. Fully compliant, permanent alarms must be installed by the date given. There were no smoke alarms in the apartmen building.	t	
NFPA 1-11.1.7.6		Extension cords may not be used as a substitute for permanent wiring.		Extension cords being used for permanent wiring. Heater located on the second & third floor apartment. Extension cord being used with heat tape located in the basement.	5/23/2018	
NFPA 101-9.1.2; NFPA 70		All electrical equipment must comply with the National Electric Code.		Junction box located in the basement by the water heater needs a cover.	5/23/2018	
		Existing stairs must have a handrail on at least one side.		Front and rear stairs need hand rails.	5/23/2018	
		Porches must be good repair, and		Rear porch is structurally unsafe.	4/30/2018	
backup Carb required in ea		backup Carbon	ardwired with battery Monoxide alarms are unit, and on each pasements.	IMMEDIATELY install temporary CO alarms where required. Fully compliant, permanent alarms must be installed by the date given. Need a CO detector in each apartment and in the basement.	5/23/2018	
NFPA 101-31.3	3.2	Boiler and fuel-fired heaters serving more than one dwelling unit must have 1-hour separation or sprinkler protection.		Need protection over both water heaters and the furnace.	5/23/2018	
NFPA 101-31.2	2.2.1	1-hour fire rated doors and assemblies required, including self-closing and self-latching mechanisms.		All apartment front and rear entry doors and the basement door.	10/20/2018	
NFPA 101-Ch.	8	The fire barrier, including walls, ceilings, floors, etc. must be maintained with the minimum required fire rating.		The front and rear hallway have excessive holes in the walls and ceilings.	5/23/2018	
LTRFI-001214-20	018	Long Term Ren	tal Registration	4/23/2018	Canceled	
LTRIN-005868-20	118	Long Term Ren	tal Pogistration	8/20/2018	Scheduled	

Inspection Comment: Scheduled w/ owner John 8.8.18