CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

August 18, 2017

Responsible Party 1:				
FREDERICK MARINA				
79 Spindle Rd				
Ellsworth, ME 04605				
Location	CBL	Inspection Date		
Location 208 PARK AVE	CBL 053 B006001	Inspection Date 7/31/2017		
		=		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 9/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101- 8.3.5 HOLE IN WALL NEEDS REPAIR; The provisions of 8.3.5 shall govern the materials and mathods of construction used to protect through-penetrations and membrane penetrations in fire walls, fire barrier walls, and fire resistance-rated horizontal assemblies. The provisions of 8.3.5 shall not apply to approved existing materials and methods of construction used to protect existing through-penetrations and existing membrane penetrations in fire walls, fire barrier walls, or fire resistance-rated horizontal assemblies, unless otherwise required by chapters 11 though 43. Any holes in the walls of the basement, common areas and stairwells must be repaired.	
NFPA 80- ANNEX D.4 1-HOUR FIRE DOORS ASSEMBLIES REQ; Listings are provided for floor fire door assemblies that are installed in fire-rated floor-ceiling or roof-ceiling assemblies that have been tested in accordance with the methods described in NFPA 288. The listing indicates the fire-rated assembly and the hourly rating (3 hours, 2 hours, 1.5 hours, 1 hour, .75 hours) for which the door can be permitted to be used so that access to the space above the ceiling or to the floor above can be provided without adversely affecting the fire resistance rating of the entire assembly. The listing provides limitations on the maximum size of an individual door opening and the total area of all door openings permitted for each 100 square feet of floor or ceiling.	
All apartment doors that enter a stairwell or common area to include the basement door must be 60 minute rated self-closing fire doors with tags indentifying thei fire rating.	

Violation		Proposed Date of Completion
shall be powered in accordance we hardwired with battery back up that is capable of operating the dehardwired and replaced every 10 All new smoke alarms shall be ph	O SMOKE DETECTORS REQUIRED; New smoke alarms with NFPA 72. Where available options include: A non-rechargeable, non-replaceable primary battery evice for at leat 10 years Existing smoke alarms shall be years with smoke alarms complying with the above notes. notoelectric.	
FINAL DATE OF COMPLETED	VIOLATION(S)	//
FIRE PREVENTION BUREAU R	E-INSPECTION OF COMPLETED VIOLATION(S)	//
_	o reject or modify any proposed plan of action, and may all capacity to complete the proposed plan. Please contact ON	-
•	s listed within the timeframes provided. If I require add the Fire Prevention Bureau <u>prior to the deadline</u> to requal discretion to grant or deny.	
· ·	my responsibility to schedule a reinspection of my prope My failure to schedule a reinspection shall be deemed an lied.	•
	eement, I understand that I am liable for penalties pursu §§ 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be	• •
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	<u></u>