Portland, Maine



Yes. Life's good here.

August 3, 2015

DANILUK DARYN A

837 CONGRESS ST # 3

PORTLAND, ME 04102

CBL: 053 C022001

Located at 837 CONGRESS ST

NOTICE OF INTENT TO PROSECUTE

Dear Owner/Manager/Occupant,

An inspection of the property located at the above referenced address on 07/31/2015 revealed that the structure and premises fail to comply with NFPA 2009 Fire Code and/or NFPA Life Safety Codes. Attached is a list of those violations.

The above-referenced property is in violation of the Chapter 10, Fire Prevention and Protection, Article 1 of the Portland City Code (the "Code") and National Fire Protection Association (NFPA) 101 Life Safety Code. Please note that the Code is available online at www.portlandmaine.gov.

This is a notice of intent to prosecute. As such, the matter is being referred to the City of Portland Corporation Council for legal action and possible civil penalties as provided for in Chapter 10, Fire Prevention and Protection, 10-25 of the Code and in Title 30- A.M.R.S.A. 4452.

Please be advised that you will need to contact the Fire Prevention Bureau at 207-874-8400 before the court date on the attached Reference to Court letter to either schedule a re-inspection or to submit a plan of action to correct these violations.

Sincerely,

Portland Fire Department

Fire Prevention Bureau

CITY OF PORTLAND PORTLAND FIRE DEPARTMENT

380 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager DANILUK DARYN A			Inspector Daniel Dyer		Inspection Date
					7/31/2015
Location	CBL		Status		Inspection Type
837 CONGRES	S ST 053	C022001	Failed		Fire Company-FP Routine Inspec
Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1) 80.82					
	NFPA 101- 7.2.2.5.1.1 EXIT STAIRS NOT SEPARATED.; ALL INSIDE STAIRS SERVING AS AN EXIT OR EXIT COMPONENT SHALL BE ENCLOSED IN ACCORDANCE WITH 7.1.3.2.				
Notes: 2	2ND FLOOR				
2) 55.25					
or ad	NFPA 101- 31.3.4.5.1 SMOKE ALARMS REQUIRED; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements.				
Notes: R	REPLACE MISSING DETECTORS				
3) 89.05					
	NFPA 1- EXCESSIVE/DISORDERLY STORAGE; REFERENCE NFPA 1 FOR EXCESSIVE FUEL-LOAD.				
Notes: B	ASEMENT				

Comments:

DISTRICT COURT Location: Portland Docket No.

CITY OF PORTLAND and body politic and Corporate, located in the County of Cumberland and State of Maine,

Plantiff,

FIRE PREVENTION AND PROTECTION CODE VIOLATION

(M.R. CIV. P. 80H AND 80k)

v.

Daryn Daniluk Defendant

SUMMONS NUMBER:

353823

This matter has been referred to the Corporation Counsel's Office for immediate legal action with respect to the code violations detailed in the attached letter. It has been assigned the above summons number and will be filed with the Portland District Court and will be assigned for an initial appearance at the Portland District Court 205 Newbury Street Portland, Maine 04101 at 8:30 A.M. on 09/14/2015. I strongly urge you to contact Victoria Meserve at Fire Prevention at (207)-874-8400 or via e-mail at meservev@portlandmaine.gov to set up an inperson meeting to resolve these issues or make alternative arrangements to relieve you of the requirement to appear in Court on 09/14/2015.

Datad: 0

Adam R. Lee, Esq. Bar No. 4143

Associate Corporation Council

City of Portland 389 Congress St

Portland, ME 04101

207-874-8480