CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

October 25, 2017

Responsible Party 1:				
Berenson Gail Susan				
220 BRACKETT ST #2				
PORTLAND, ME 04102				
Location	CBL	Inspection Date		
Location 220 BRACKETT ST	CBL 055 B038001	Inspection Date 9/21/2017		
		-		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 11/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101- 31.3.1.1.1 VERTICAL OPENINGS NOT FIRE RATED ; Vertical openings shall be enclosed or protected in accordance with Section 8.6. Second floor front room.	//
NFPA 101- 7.2.1.8.1 FIRE DOORS MUST BE SELF- OR AUTO-CLOSING; A door leaf normally required to be kept closed shall not be secured in the open position at any time and shall be self-closing or automatic-closing in accordance with 7.2.1.8.2, unless otherwise permitted by 7.2.1.8.3. All fire doors must self-close and latch. Check self-closing operation prior to re-inspection.	//
NFPA 720- 5.5.6.1 CO ALARMS REQUIRED; The performance, location, and mounting of notification appliances used to initiate or direct action, evacuation or relocation of the occupants, or for providing information to occupants or staff, shall comply with the requirements of Chapter 6. first floor, basement	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
NFPA 101- 31.3.4.5.1 SMOKE ALARMS REQUIRED; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements. In the Basement. First floor bedroom was locked, access must be gained on a re-inspection.	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
NFPA 1 EXCESSIVE/DISORDERLY STORAGE; Reference NFPA 1 for excessive fuel-load. second floor front, basement	//

Violation		Proposed Date of Completion
31.3.2.1.1 shall be protected as	PROTECTION REQUIRED; The areas described in Table indicated: Boiler and fuel-fired heater rooms serving more num separation/protection is 1 hour or sprinklers)	//
	FIRE DOOR REQUIRED; Refer to NFPA 101- Table 8.3.4.2 for vertical shafts (including stairways, exits, and refuse or 1 hour.	//
FINAL DATE OF COMPLETED	VIOLATION(S)	//
FIRE PREVENTION BUREAU	RE-INSPECTION OF COMPLETED VIOLATION(S)	//
	to reject or modify any proposed plan of action, and may cal capacity to complete the proposed plan. Please contaction	=
•	ns listed within the timeframes provided. If I require add t the Fire Prevention Bureau <u>prior to the deadline</u> to requ s discretion to grant or deny.	
· ·	my responsibility to schedule a reinspection of my prope My failure to schedule a reinspection shall be deemed an died.	•
	reement, I understand that I am liable for penalties pursu §§ 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be	• •
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	