## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

WILLIAM FOX PO BOX 3777 HALLANDALE FL 33008 December 7, 2017

Location	CBL	<b>Inspection Date</b>
39 SPRUCE ST	056 D032001	11/7/2017
Inspector	Inspection Type	Status
Gene Cote	FP Routine Inspection	Failed

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 12/30/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
PORTLAND FIRE DEPARTMENT CHAPTER 10 4.6.1, 4.6.2 UNIT/SUITE NUMBERS NOT MARKED; 4.6.1 Residential units shall be designated using numerals. 4.6.2 The first numeral of each residential unit shall be the floor designation. each unit front and rear stairwell	//
NFPA 101- 31.3.1.1.1 VERTICAL OPENINGS NOT FIRE RATED; Vertical openings shall be enclosed or protected in accordance with Section 8.6. In the closet on first floor under stairs and above the basement stairs.	//
NFPA 101-31.3.2.1 AND 31.3.2.1.1 PROTECTION OF HAZARDOUS AREAS NOT PROVIDED; Any hazardous area shall be protected in accordance with Section 8.7. The areas described in Table 31.3.2.1.1 shall be protected as indicated.  3 story attached shed has no fire rated seperation to the rear stairs.	//
NFPA 101- 7.2.8.5.1 HANDRAILS REQUIRED ON STAIRS; All fire escape stairs shall have walls or guards and handrails on both sides in accordance with 7.2.8.4.1 (b).  3rd floor	//
NFPA 101-7.10.5.1 NORMAL ILLUMINATION FOR EXITS; Every sign required by 7.10.1.2, 7.10.1.5, or 7.10.8.1, other than where operations or processes require low lighting levels, shall be suitably illuminated by a reliable light source. Externally and internally illuminated signs shall be legible in both the normal and emergency lighting mode.  Rear stairwell	//
NFPA 1 EXCESSIVE/DISORDERLY STORAGE; Reference NFPA 1 for excessive fuel-load.  Rear stairwell kept clear of all storage	//

Violation		Proposed Date of Completion
NFPA 54 UNPROTECTED OUTS outdoor unprotected gas lines. meters and line have no protection	SIDE GAS LINE; See NFPA 54 regarding requirements for	//
31.3.2.1.1 shall be protected as ir	ROTECTION REQUIRED; The areas described in Table ndicated: Boiler and fuel-fired heater rooms serving more um separation/protection is 1 hour or sprinklers) s water heaters in basement	//
	IRE DOOR REQUIRED; Refer to NFPA 101- Table 8.3.4.2 or vertical shafts (including stairways, exits, and refuse r 1 hour.	//
FINAL DATE OF COMPLETED	VIOLATION(S)	//
FIRE PREVENTION BUREAU R	E-INSPECTION OF COMPLETED VIOLATION(S)	//
understand that I must contact is entirely within the Bureau's I further understand that it is have been remedied to do so. I violations have not been remediated to comply with this agree.	s listed within the timeframes provided. If I require addithe Fire Prevention Bureau prior to the deadline to requisoretion to grant or deny.  The property of the series of the deadline to requisite the series of	test an extension, which  ty once the violations  admission that the  ant to the City of
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	