

Planning & Urban Development Department

Director of Planning and Urban Development Jeff Levine

> Inspection Services, Director Tammy M. Munson

October 20, 2015

SEA OTTER TAYLOR LIMITED 39 COVESIDE LN YARMOUTH, ME 04096

CBL: 057 B009001

Located at: 12 TAYLOR ST

Certified Mail 7010 1870 0002 8136 9418

To whom it may concern:

SECOND NOTICE OF VIOLATION

An evaluation of the above-referenced property on 10/20/2015 revealed that the structure remains non-compliant with the Housing Code of the City of Portland.

Attached is a list of the violations.

This is a **SECOND** notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected. A re-inspection will occur on 11/03/2015, at which time compliance will be required.

Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code and in Title 30-A M.R.S.A ss 4452.

Please feel free to contact me is you wish to discuss this matter further or have any questions.

Sincerely,

Chuck Fagone

Code Enforcement Officer

(207) 874-8789

CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager Sea Otter Taylor Limited		Inspector	Inspection Date
		Chuck Fagone	10/20/2015
Location	CBL	Status	Inspection Type
12 TAYLOR ST	057 B009001	Re-Inspect 14 Days	Building-Inspection

Code	Int/Ext	Floor	Unit No.	Area	Compliance Date

1) 22.3.3(a)

Exterior

Yard

Violation:

PREMISES TO BE KEPT FREE FROM RODENT HARBORAGE

The owner of a two (2) or more family residential building and the owner or occupant of a single family residential building shall maintain the building and the lot on which the building is located free from any accumulation of any putrid substance, garbage, rubbish, old lumber, debris or rubble,

except in watertight covered containers.

Notes:

Second notice as the property is still not in compliance. Trash barrel on the side of the building. In the rear yard, mattress, brush, wood stove and other debris will need removal. If not completed by the next

inspection, a \$150 re-inspection fee will be assessed to the property.