CITY OF PORTLAND

FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

February 16, 2018

JASON BICKNELL 97 SALEM ST PORTLAND ME 04102

Location	CBL	Inspection Date
93 SALEM ST	057 H006001	1/9/2018
Inspector	Inspection Type	Status
Robert Mcpartlan	FP Routine Inspection	Failed

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must remedy each violation prior to the date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 3/15/2018.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 70- ARTICLE 110.12 B EXPOSED WIRING CONNECTIONS ; Internal parts of electrical equipment, including busbars, wiring terminals, insulators, and other surfaces, shall not be damaged or contaminated by foreign materials such as paint, plaster, cleaners, abrasives, or corrosive residues. There shall be no damaged parts that may adversely affect safe operation or mechanical strength of the equipment such as parts that are broken; bent; cut; or deteriorated by corrosion, chemical reaction, or overheating. need juction box cover. Middle unit at bottom of basement stairs	3/15/2018
NFPA 101- 31.3.2.1.1 BOILER PROTECTION REQUIRED ; The areas described in Table 31.3.2.1.1 shall be protected as indicated: Boiler and fuel-fired heater rooms serving more than a single dwelling unit (minimum separation/protection is 1 hour or sprinklers) need sprinkler head over boiler in middle unit	3/15/2018
NFPA 70- ARTICLE 110.12 B EXPOSED WIRING CONNECTIONS ; Internal parts of electrical equipment, including busbars, wiring terminals, insulators, and other surfaces, shall not be damaged or contaminated by foreign materials such as paint, plaster, cleaners, abrasives, or corrosive residues. There shall be no damaged parts that may adversely affect safe operation or mechanical strength of the equipment such as parts that are broken; bent; cut; or deteriorated by corrosion, chemical reaction, or overheating. need cover for light switch at front door of middle unit	3/15/2018
NFPA 101- 9.1.2 CERTIFY ELECTRICAL SYSTEM ; Electrical wiring and equipment shall be in accordance with NFPA 70, unless such installations are approved existing installations, which shall be permitted to be continued in service. In the middle apartment, there is a grow operation. A licensed electrician must evaluate the setup and provide a letter to the Fire Prevention Bureau that the operation is not overpowering the electrical system for the property.	3/15/2018

Violation	Proposed Date of Completion
FINAL DATE OF COMPLETED VIOLATION(S)	/
FIRE PREVENTION BUREAU RE-INSPECTION OF COMPLETED VIOLATION(S) Reinspection scheduled for March 26, 2018 at 2:00pm.	<u>3 /26 /2018</u>

The Bureau reserves the right to reject or modify any proposed plan of action, and may require evidence of sufficient financial and technical capacity to complete the proposed plan. Please contact the Bureau with any questions.

VIOLATOR CERTIFICATION

I agree to remedy the violations listed within the timeframes provided. If I require additional time to comply, I understand that I must contact the Fire Prevention Bureau <u>prior to the deadline</u> to request an extension, which is entirely within the Bureau's discretion to grant or deny.

If I fail to comply with this agreement, I understand that I am liable for penalties pursuant to the City of Portland Code of Ordinances §§ 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be subject to further legal action.

Date	Responsible Party
Date	Responsible Party
SEEN AND AGREED	

Date

Fire Prevention Bureau