## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

September 22, 2017

Responsible Party 1:				
Spaien Gail				
16 Angell Ave				
South Portland, ME 04106				
Location	CBL	Inspection Date		
Location 35 SALEM ST	<b>CBL</b> 057 J025001	Inspection Date 8/22/2017		
		•		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 10/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
PORTLAND FIRE DEPARTMENT CHAPTER 10 4.3.1, 4.3.2 BUILDING ADDRESS NOT MARKED ON BUILDING; 4.3.1 Signs shall be located in a position readily visible as approaching from the main access and approved by the Fire Department. Signs shall be illuminated or retro reflective on a contrasting background and the letter(s) size shall be approved by the Fire Department. 4.3.2 Street Address shall be clearly marked on the front of the building and building sign as approved by the Fire Department. Address not marked on front of building	//
PORTLAND FIRE DEPARTMENT CHAPTER 10 4.6.1, 4.6.2 UNIT/SUITE NUMBERS NOT MARKED; 4.6.1 Residential units shall be designated using numerals. 4.6.2 The first numeral of each residential unit shall be the floor designation. Unit numbers must be labeled	//
NFPA 101- 7.2.1.15.8 FIRE DOOR ASSEMBLY REQ REPAIR; Door openings not in proper operating condition shall be repaired or replaced without delay.  Self closures needed in multiple locations on fire doors. 3rd floor front, 3rd floor rear, 2nd floor rear.	//
NFPA 720- 5.5.6.1 CO ALARMS REQUIRED; The performance, location, and mounting of notification appliances used to initiate or direct action, evacuation or relocation of the occupants, or for providing information to occupants or staff, shall comply with the requirements of Chapter 6.  Required in all units	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.

Violation		Proposed Date of Completion
through out with an existing, complete au be installed in accordance with 9.6.2.10,	<b>REQUIRED</b> ; In buildings other than those equipped tomatic smoke detection system, smoke alarms shall as modified by 31.3.4.5.2, outside every sleeping coms and on all levels of the dwelling unit, including	IMMEDIATELY install
<b>NFPA 70 MISSING BOX COVERS</b> ; Refer for missing box covers.  Missing junction box cover in basement r	er to NFPA 70, National Electrical Code, on standards near hot water heaters	//
		//
FINAL DATE OF COMPLETED VIOLAT	TION(S)	//
FIRE PREVENTION BUREAU RE-INSP	ECTION OF COMPLETED VIOLATION(S)	//
understand that I must contact the First is entirely within the Bureau's discret I further understand that it is my resphave been remedied to do so. My fails violations have not been remedied.  If I fail to comply with this agreement.	within the timeframes provided. If I require add re Prevention Bureau prior to the deadline to requion to grant or deny.  consibility to schedule a reinspection of my properure to schedule a reinspection shall be deemed and I understand that I am liable for penalties pursuand 10-25, and 30-A M.R.S. § 4452 and may be	nest an extension, which  rty once the violations  and admission that the  ant to the City of
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	