

194 Danforth St.

June 30, 2015

Scope of Repairs existing Front Entry

Install new wood pressure treated stair treads (12) - $5\frac{1}{2}$ " X 6"

Install new wood balusters. Repair wood columns and railings.
same

Paint all owners color choice.