

DEGEOVED APR 28 2017

By

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

April 13, 2017

Responsible Party 1:		
Zemans Grete	•	
194 Danforth St		
Portland, ME 04102		
Location	CBL	Inspection Date
Location 194 DANFORTH ST	<b>CBL</b> 057 K006001	Inspection Date 3/29/2017
		•

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 4/30/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements.	Proposed Date of Completion
enclosed or protected in accordance with Section 8.6. Install a 1 hr fire seperation in above and below the dumbwaiter opening at the second floor landing in the rear stairs.  NFPA 101- 31.3.4.5.1 SMOKE ALARMS REQUIRED; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements.  Install hardwired smoke detectors in apartments 2 and 3 in the living room (Immediately outside the bedroom is not possible do to the kitchen location)  NFPA 70 MISSING BREAKER IN PANEL; Refer to NFPA 70, National Electrical Code, for information on missing breakers in an electrical panel.	//
through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements.  Install hardwired smoke detectors in apartments 2 and 3 in the living room (Immediately outside the bedroom is not possible do to the kitchen location)  NFPA 70 MISSING BREAKER IN PANEL; Refer to NFPA 70, National Electrical Code, for information on missing breakers in an electrical panel.	5/8/17 Vyuy #
information on missing breakers in an electrical panel.	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
	5/8/17 V Valy
NFPA 101- 8.3.4.2 60 MINUTE FIRE DOOR REQUIRED; Refer to NFPA 101- Table 8.3.4.2 that states fire door assemblies for vertical shafts (including stairways, exits, and refuse chutes) are rated and required for 1 hour.  All apartment doors must be fire rated and have a rating tag attached to each door.	MI POOR SAIR LAND

\* Business card of person doing all repairs enclosed (\* I do not understand this I asked Inspector Brennan how I would know if my fire escape was in apond working order. He said he would send me trame of person who could inspect it. No mention of it not being in aperating condition or needing regains.

Violation		Proposed Date of Completion
FINAL DATE OF	COMPLETED VIOLATION(S)	5/8/2017
FIRE PREVENTION	ON BUREAU RE-INSPECTION OF COMPLETED	VIOLATION(S)//

The Bureau reserves the right to reject or modify any proposed plan of action, and may require evidence of sufficient financial and technical capacity to complete the proposed plan. Please contact the Bureau with any questions.

## VIOLATOR CERTIFICATION

I agree to remedy the violations listed within the timeframes provided. If I require additional time to comply, I understand that I must contact the Fire Prevention Bureau <u>prior to the deadline</u> to request an extension, which is entirely within the Bureau's discretion to grant or deny.

I further understand that it is my responsibility to schedule a reinspection of my property once the violations have been remedied to do so. My failure to schedule a reinspection shall be deemed an admission that the violations have not been remedied.

If I fail to comply with this agreement, I understand that I am liable for penalties pursuant to the City of Portland Code of Ordinances §§ 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be subject to further legal action.

4/25/2017	Frete Zemans		
Date '	Responsible Party		
Date	Responsible Party		
SEEN AND AGREED			
5/2/2017	Copt. D. Retull (Rétruccelli)		
Date	Fire Prevention Bureau		

in re: \*\* this is not for fire escape. This relates to the fire door and the door jamb, latch, trim that make up the door assembly