CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

November 16, 2017

Location	CBL	Inspection Date	
12 SALEM ST	058 B005001	10/12/2017	
Inspector	Inspection Type	Status	
John Brennan	FP Routine Inspection	Failed	

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 12/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101- 31.3.1.1.1 VERTICAL OPENINGS NOT FIRE RATED ; Vertical openings shall be enclosed or protected in accordance with Section 8.6. Front 3rd floor stairwell ceiling needs patching.	//
NFPA 101- 8.3.4.2 60 MINUTE FIRE DOOR REQUIRED; Refer to NFPA 101- Table 8.3.4.2 that states fire door assemblies for vertical shafts (including stairways, exits, and refuse chutes) are rated and required for 1 hour. 60 minute fire rated doors with self-closing hardware are needed in the following locations: Basement, both front and rear entry doors for unit 2, Unit 3 front door.	//
NFPA 101- 7.2.1.8.1 FIRE DOORS MUST BE SELF- OR AUTO-CLOSING; A door leaf normally required to be kept closed shall not be secured in the open position at any time and shall be self-closing or automatic-closing in accordance with 7.2.1.8.2, unless otherwise permitted by 7.2.1.8.3. All FIRE doors need self closing hinges.	//
NFPA 101- 7.2.8.5.1 HANDRAILS REQUIRED ON STAIRS ; All fire escape stairs shall have walls or guards and handrails on both sides in accordance with 7.2.8.4.1 (b). front porch does not have handrail.	//
NFPA 1 EXCESSIVE/DISORDERLY STORAGE; Reference NFPA 1 for excessive fuel-load. Hallways/stairwells should not have any storage. FLOOR 3 LANDING HAS EXTENSIVE STORAGE AND AN ELECTRIC WASHER AND DRYER. REMOVE ALL ITEMS OR MOVE APARTMENT FIRE DOOR TO THE BOTTOM OF THE STAIRS.	//

Violation		Proposed Date of Completion
wiring installations shall be provide only to temporary wiring installation personnel during construction, rem structures, equipment, or similar ad	RDS; Ground-fault protection for personnel for all temporary d to comply with 590.6(A) and (B). This section shall apply as used to supply temporary power to equipment used by odeling, maintenance, repair, or demolition of buildings, ctivities. ORDS SECURED TO PIPES RUNNING FROM 1ST	//
FINAL DATE OF COMPLETED V	IOLATION(S)	//
FIRE PREVENTION BUREAU RE	-INSPECTION OF COMPLETED VIOLATION(S)	//
<u> </u>	reject or modify any proposed plan of action, and may a capacity to complete the proposed plan. Please contact	-
•	listed within the timeframes provided. If I require addi he Fire Prevention Bureau <u>prior to the deadline</u> to requ iscretion to grant or deny.	_ ·
	y responsibility to schedule a reinspection of my proper ly failure to schedule a reinspection shall be deemed an ed.	•
	ement, I understand that I am liable for penalties pursua § 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be s	• •
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	