
## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400



## NOTICE OF VIOLATION AND ORDER TO CORRECT

December 1, 2016

Responsible Party 1: Martelle Matthew	2	×	
12 SALEM ST		21	1
PORTLAND, ME 04102			
Location 12 SALEM ST	CBL 058 B005001	Inspection Date 11/17/2016	3 %
Inspector Angela Calvo	Inspection Type FP Routine Inspection	Status Failed	

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must complete the proposed date of completion column by proposing a reasonable timeframe to remedy each violation. This form must be received by the Fire Prevention Bureau no later than 12/30/2016. The Bureau reserves the right to reject or modify any proposed plan of action, and may require evidence of sufficient financial and technical capacity to complete the proposed plan. Please contact the Bureau with any questions.

YOUR FAILURE TO SUBMIT A PLAN OF ACTION BY THE DATE PROVIDED, OR TO CORRECT ANY VIOLATION WITHIN THE APPLICABLE TIME FRAME, MAY RESULT IN LEGAL ACTION AGAINST YOU, THE IMPOSITION OF CIVIL PENALTIES, AND THE PURSUIT OF OTHER LEGAL REMEDIES.

Violation	Proposed Date of Completion
PORTLAND FIRE DEPARTMENT CHAPTER 10 4.6.1, 4.6.2 UNIT/SUITE NUMBERS NOT MARKED; 4.6.1 Residential units shall be designated using numerals. 4.6.2 The first numeral of each residential unit shall be the floor designation.  Unit numbers needed throughout	1 /30 /17 Accepted by FPB
NFPA 101- 7.2.1.8.1 FIRE DOORS MUST BE SELF- OR AUTO-CLOSING; A door leaf normally required to be kept closed shall not be secured in the open position at any time and shall be self-closing or automatic-closing in accordance with 7.2.1.8.2, unless otherwise permitted by 7.2.1.8.3.  All doors need slef closing hinges	2 /38 /19 9/1/2017 per FPB
NFPA 101-7.2.8.5.1 HANDRAILS REQUIRED ON STAIRS; All fire escape stairs shall have walls or guards and handrails on both sides in accordance with 7.2.8.4.1 (b).  front porch does not have handrail	2 /28/18 9/1/2017 per FPB
NFPA 101-31.3.4.5.1 SMOKE ALARMS REQUIRED; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements.  needed throughout to include bedrooms in units	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
NFPA 1 EXCESSIVE/DISORDERLY STORAGE; Reference NFPA 1 for excessive fuel-load.	2 /20/11
Hallways/stairwells should not have any storage	9/1/2017 per FPB

The Fire Prevention Bureau has determined that all violations must be corrected by the new deadline of September 1, 2017. Please call 874-8400 to make an appointment for reinspection once violations are corrected.

LANGE

## VIOLATOR CERTIFICATION

I agree to remedy the violations listed within the timeframes provided. If I require additional time to comply, I understand that I must contact the Fire Prevention Bureau <u>prior to the deadline</u> to request an extension, which is entirely within the Bureau's discretion to grant or deny.

I further understand that it is my responsibility to schedule a reinspection of my property once the violations have been remedied to do so. My failure to schedule a reinspection shall be deemed an admission that the violations have not been remedied.

Portland Code of Ordinances §§ action.	1-15 and 10-25, and 30-A M.R.S. § 4452 and may be subject to further leg	al
\( \frac{1}{30} \)	Responsible Party	in the second
Date	Responsible Party	
SEEN AND AGREED	DioPRETUL:	
Date	Fire Prevention Bureau	