

Jerome F. LaMoria Fire Chief, Fire Department

Portland Fire Department Fire Prevention Bureau 380 Congress St Portland, ME 04101

April 30, 2015

Sea Otter 12G LLC 39 Coveside Ln Yarmouth, ME 04096

NOTICE OF INTENT TO PROSECUTE

Dear Owner/Manager/Occupant,

An inspection of the property located at 12 Gilman St on 04/16/2015 revealed that the structure and premises fail to comply with NFPA 2009 Fire Code and/or NFPA Life Safety Codes. Attached is a list of those violations.

The above-referenced property is in violation of the Chapter 10, Fire Prevention and Protection, Article 1 of the Portland City Code (the "Code") and National Fire Protection Association (NFPA) 101 Life Safety Code. Please note that the Code is available online at www.portlandmaine.gov.

This is a notice of intent to prosecute. As such, the matter is being referred to the City of Portland Corporation Council for legal action and possible civil penalties as provided for in Chapter 10, Fire Prevention and Protection, 10-25 of the Code and in Title 30- A.M.R.S.A. 4452.

Please be advised that you will need to contact the Fire Prevention Bureau at 207-874-8400 before the court date on the attached summons to either schedule a re-inspection or to submit a plan of action to correct these violations.

Sincerely,

Portland Fire Department Fire Prevention Bureau

A/C With Sauteur

DISTRICT COURT Location: Portland Docket No.

CITY OF PORTLAND and body politic and Corporate, located in the County of Cumberland and State of Maine,

Plantiff,

FIRE PREVENTION AND PROTECTION CODE VIOLATION

(M.R. CIV. P. 80H AND 80k)

v.

Sea Otter 12G Limited Defendant

SUMMONS NUMBER:

353732

This matter has been referred to the Corporation Counsel's Office for immediate legal action with respect to the code violations detailed in the attached letter. It has been assigned the above summons number and will be filed with the Portland District Court and will be assigned for an initial appearance at the Portland District Court 205 Newbury Street Portland, Maine 04101 at 8:30 A.M. on June 8, 2015. I strongly urge you to contact Victoria Meserve at Fire Prevention at (207)-874-8400 or via e-mail at meservev@portlandmaine.gov to set up an inperson meeting to resolve these issues or make alternative arrangements to relieve you of the requirement to appear in Court on June 8, 2015.

Dated: $4/30/\iota$

Adam R. Lee, Esq. Bar No. 4143

Associate Corporation Council

City of Portland 389 Congress St

Portland, ME 04101

207-874-8480

CITY OF PORTLAND PORTLAND FIRE DEPARTMENT

Summans # 353732

380 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager SEA OTTER 12G LIMITED				Inspector Craig Messinger		Inspection Date 4/16/2015
12 GILMAN ST	T	064 E	020001	Failed		Fire Prevention-FP Routine Inspe
Code	ln	t/Ext	Floor	Unit No.	Area	Compliance Date
1) 9.002						
						REQ; Listings are provided for floor fire roof-ceiling assemblies that have ben

Notes:

openings permitted for each 100 ft. squared of floor or ceiling.

THIRD FLOOR, REAR EGRESS, LANDING NEEDS TO BE REBUILT, CLEANED OF DEBRIS.

tested in accordance with the methods described in NFPA 288. The listing indicates the fire-rated assembly and the hourly rating (3 hours, 2 hours, 1.5 hours, 1 hour, .75 hours) for which the door can be permitted to be used so that access to the space above the ceiling or to the floor above can be provided without adversely affecting the fire resistance rating of the entire assembly. The listing provides limitations on the maximum size of an individual door opening and the total area of all door

FIRE DOOR ADDED.

2) 55.455

Violation:

SPRINKLER SYSTEM PER 9.7

Notes:

SPRINKLER PROTECTION SHOULD BE PROVIDED IN BASEMENT W/I 10 FEET OF FUEL FIRED

HEATING DEVICES.

3) 55.080

Violation:

ELECTRICAL VIOLATION

Notes:

OPEN JUNCTION BOXES AND ELECTRICAL WIRING IN HALLWAYS.

4) 8.001

Violation:

NFPA 101- 9.6.10.1.1 SMOKE DETECTOR REQUIRED; Where required by another section of this code, single-station and multiple-station smoke alarms shall be inaccordance with NFPA 72, National Fire Alarm Code, shall be provided in all occupiable areas in environments that are suitable for proper

smoke detector operation.

Notes:

DETECTION IN BASEMENT AND HALLWAYS INCLUDING CARBON MONOXIDE SHOULD BE

PROVIDED.

Comments: