CITY OF PORTLAND

FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

January 17, 2018

RAHMON LLC PO BOX 6149 FLMOUTH ME 04105

Location	CBL	Inspection Date
105 GILMAN ST	065 E007001	12/8/2017
Inspector	Inspection Type	Status
Alan Greene	FP Routine Inspection	Failed

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 2/15/2018.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101- 7.2.2.4.2 HANDRAILS ARE NOT CONTINOUS ; Required guards and hardrails shall continue for the full length of each flight of stairs. At turns of new stairs, inside handrails shall be continuous between flights at landings. Throughout	
NFPA 101- 31.3.1.1 VERTICAL OPENING VIOLATIONS ; Vertical openings shall comply with 31.3.1.1.1 through 31.3.1.2. 3 rd floor rear stairs. Ceiling not 1 hour fire rated, scuttle not rated.	
NFPA 101- 7.1.3.2.1 60-MIN FIRE DOOR ASSEMBLIES REQ ; The separation shall have a minimum 1-hour fire resistance rating where the exit connects three or fewer stories. Basement door rear	
NFPA 101- 7.2.1.8.1 DOORS SHALL BE SELF-CLOSING & SELF-LATCHING ; A door leaf normally required to be kept closed shall not be secured in the open position at any time and shall be self-closing or automatic-closing in accordance with 7.2.1.8.2, unless otherwise specified by 7.2.1.8.3.	
Throughout. None of the fire doors are self closing. NFPA 101- 31.1.5.1 ELECTRICAL VIOLATION ; Utilities shall comply with the provisions of	
section 9.1.	
Defunct electrical panel and associated wiring need to be removed.	
NFPA 101- 31.3.2.1.1 BOILER PROTECTION REQUIRED ; The areas described in Table 31.3.2.1.1 shall be protected as indicated: Boiler and fuel-fired heater rooms serving more than a single dwelling unit (minimum separation/protection is 1 hour or sprinklers)	

Violation	Proposed Date of Completion
NFPA 101- 31.3.1.1 VERTICAL OPENING VIOLATIONS ; Vertical openings shall comply with 31.3.1.1.1 through 31.3.1.2.	
Front stairway celing not fire rated, 3rd floor.	
FINAL DATE OF COMPLETED VIOLATION(S)	//
FIRE PREVENTION BUREAU RE-INSPECTION OF COMPLETED VIOLATION(S)	//

The Bureau reserves the right to reject or modify any proposed plan of action, and may require evidence of sufficient financial and technical capacity to complete the proposed plan. Please contact the Bureau with any questions.

VIOLATOR CERTIFICATION

I agree to remedy the violations listed within the timeframes provided. If I require additional time to comply, I understand that I must contact the Fire Prevention Bureau <u>prior to the deadline</u> to request an extension, which is entirely within the Bureau's discretion to grant or deny.

I further understand that it is my responsibility to schedule a reinspection of my property once the violations have been remedied to do so. My failure to schedule a reinspection shall be deemed an admission that the violations have not been remedied.

If I fail to comply with this agreement, I understand that I am liable for penalties pursuant to the City of Portland Code of Ordinances §§ 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be subject to further legal action.

Date

Responsible Party

Date

Responsible Party

SEEN AND AGREED

Date

Fire Prevention Bureau