CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

January 4, 2017

Responsible Party 1:				
Ackley Kimberly				
53 Waterhouse Rd				
Gorham, ME 04038				
Location	CBL	Inspection Date		
Location 58 ROBERTS ST	CBL 066A F006001	Inspection Date 12/22/2016		
		_		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must complete the proposed date of completion column by proposing a reasonable timeframe to remedy each violation. This form must be received by the Fire Prevention Bureau no later than 1/30/2017. The Bureau reserves the right to reject or modify any proposed plan of action, and may require evidence of sufficient financial and technical capacity to complete the proposed plan. Please contact the Bureau with any questions.

YOUR FAILURE TO SUBMIT A PLAN OF ACTION BY THE DATE PROVIDED, OR TO CORRECT ANY VIOLATION WITHIN THE APPLICABLE TIME FRAME, MAY RESULT IN LEGAL ACTION AGAINST YOU, THE IMPOSITION OF CIVIL PENALTIES, AND THE PURSUIT OF OTHER LEGAL REMEDIES.

Violation	Proposed Date of Completion
NFPA 10- 7.2.4.4 FIRE EXTINGUISHER INSPECTION TAG; Where manual inspections are conducted, records for manual inspections shall be kept on a tag or label attached to the fire extinguisher, on an inspection checklist maintained on file, or by an electronic method. No tag on extinguisher at top of basement stairs	//
NFPA 101- 31.3.4.5.1 SMOKE ALARMS REQUIRED; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements. Detector in rear entry vestible not secured to wall.	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
NFPA 30- TABLE 9.6.2.1 FLAMMABLE/COMBUSTIBLE LIQUIDS STORAGE EXCEED LIMIT; See NFPA 30 Table 9.6.2.1 for special occupancy limits for flammable and combustible liquid storage. Gasoline stored in rear entry vestibule	IMMEDIATELY remove all excess flammable/combustible material from the interior of the structure. Your signature below indicates that all excess material has been removed, will not be replaced, and will be properly disposed of or stored elsewhere.

Violation		Proposed Date of Completion
NFPA 70 MISSING BOX COVERS; for missing box covers.	Refer to NFPA 70, National Electrical Code, on standards	
<u> </u>	nt lights at top of basement stairs. Firematic plug junction er attached to box.	
FIRED GRILL, CHARCOAL GRILL, HEATING, OROTHER PURPOSE, S	BACHI OR GRILL ON BALCONY; NO HIBACHI, GAS- OR OTHER SIMILAR DEVICES USED FOR COOKING, SHALL BE USED OR KINDLED ON ANY BALCONY OR N OR WITHIN 10 FTOF ANY STRUCTURE	//
NFPA 101- 8.3.4.2 60 MINUTE FIRE		//
understand that I must contact the entirely within the Bureau's discrete I further understand that it is my have been remedied to do so. My violations have not been remedied	responsibility to schedule a reinspection of my propert failure to schedule a reinspection shall be deemed an l.	st an extension, which is by once the violations admission that the
	nent, I understand that I am liable for penalties pursual -15 and 10-25, and 30-A M.R.S. § 4452 and may be s	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	— Fire Prevention Bureau	