

Concrete Construction Observation Report

Project Name:	Mercy Short Stay Hospital				Project No:	06-1069.1
Client:	Mercy Hospital				Date:	March 9, 2007
Placement Type:	Footing Wall Column Slab Other			ner 🗍		
Placement Location:	Recessed slab between lines					
PRE PLACE	MENT OBSERVATIONS		In Com	pliance	N/O	Comments
Bar Size (diameter, length, bend and anchorage)			Yes 🛛	No 🗆		As required
Location (# of bars, spacing, and cover)			Yes ⊠	No □		Within tolerances
Splicing (weld joint, overlap)			Yes ⊠	No 🗀		
Stability (wiring, chairs, and spacers)			Yes ⊠	No 🗆		Mesh laps ok, N/A rebar
Reinforcement free from mud, oil, rust, or other nonmetallic coatings			Yes ⊠	No 🗆		Wire chairs as required
Reinforcement appears in conformance to specifications			Yes ⊠	No 🗆		Acceptable
Soil subgrade prepared in accordance with project specifications			Yes 🗌	No 🗆	-	Acceptable
Defense		Date	Page	Rev.	ASTM	N/A
Barker Steel Company		2-9-07	R02		-	GRADE
		2-3-01	NU2		A 615 ⊠ A 616 □	40 🗌 50 🗌 60 🖂
					A 617	75 🗌
					A 706	A 775 Epoxy 🗌
CONCRETE PLACEMENT OBSERVATIONS						
Required mix used		In Com		<u>N/O</u>	<u>Comments</u>	
Placement and consolidation of concrete observed			Yes 🗌			
Concrete properly conveyed to all areas of placement			Yes 🗌			
Depth of layer maximum limits not exceeded			Yes 🗌			
Internal vibration (depth of insertion, spacing, time, vertical insertion,		insertion	Yes 🗌			
no conveyance of concrete by vibration)		miscratori,	Yes 🗌		\boxtimes	
Even layering around openings and embedments			Yes 🗌		\boxtimes	
Removal of temporary ties a			Yes 🗌		\boxtimes	
*CVI INDED OF THE				No 🗌		
*CYLINDER SET NO: ←*refer to associa					ted concrete t	est report
POST PLACEMENT OBSERVATIONS		In Compliance		N/O	Comments	
Specified finish			Yes 🗌		\boxtimes	
Protection of surfaces from cracking due to rapid drying		Yes 🗌		oxtimes		
Proper curing procedures implemented NON-CONFORMANCE ITEMS OBSERVED		Yes 🗌		\boxtimes		
Non-conformance item desc			Yes 🗌	No 🛛		
Action taken by SWCE:	ription:					
N/O = Not Observed			-			
	concolled due to lease of a con-				ATTA	CHMENTS Y⊠N□
NOTES: Placement was cancelled due to loss of power and subsequently due to lose the placement area, decking and reinforcing was 5 degrees Fahrenheit.				due to los	ss of	Photos
mode the placement area,	uecking and reinforcing was	5 degrees	Fahrenhe	it.		
SWCE REPRESENTATIVE: David CoWallis Jr.			REVIEWED BY:			





