## FIELD REPORT #12

SRG Engineering, Inc. P. O. Box 925 Gray, ME 04039-0925 Tel :(207)-657-7323 Fax :(207)-657-7342 Project No.:07-003Date: IProject Name:MercyProject Location:PortlatWeather Conditions:SunnyContact Person(s):StevenJim Lat

Date: May 14, 2007 Mercy Hospital Portland, Maine Sunny Steven Grant-SRG Eng. Jim Lanza-Gilbane Co.

## Discussion/Observations: LEVEL 4: GRID 3 TO 5; A to H Line

Copies To: Sean Welty-KLMK Roger Domingo-SWC James Lanza-Gilbane Paul Stevens-SMRT Janusz Wszola (EOR)-SMRT Cathy Streifel-SMRT

**Comments:** 

- 1. <u>Decking Attachments:</u> There were no locations observed with incomplete side lap and decking welds. Action Required: None.
- 2. <u>Diagonal Bracing Connections:</u> Brace connections still in progress.
- 3. **Shear Studs:** Observations noted indicate stud size, location(s), quantity, and spacing comply with project documents with the following exceptions:
  - A. W16x31 on Grid Line 3, A to B: Six (6) shear studs on the South end are located on the "weak rib" side of the deck flute. These studs were painted orange by SRG. Action Required: Either remove each and replace in the correct location, or add 3 new studs on the correct (strong) side of the deck flute.
  - B. W16x31 about 16 feet West of Grid Line 3, A to B: One (1) shear stud on the South end is located on the "weak rib" side of the deck flute. This stud was painted orange by SRG. Action Required: Either remove and correctly replace it in the correct location, or add 3 new studs on the correct (strong) side of the deck flute.
- 4. <u>Perimeter deformed reinforcement:</u> Observations noted indicate location(s), size, and spacing comply with project documents.
- 5. <u>Interior deformed reinforcement:</u> Observations noted indicate location(s), size, and spacing comply with project documents.
- 6. <u>Slab WWF reinforcement:</u> Observations noted indicate it complies with project documents.
- 7. <u>Structural Steel:</u> There were no locations observed with incomplete and/or missing connections. Action Required: None.
- 8. Jim Lanza informed SRG on May 23<sup>rd</sup> that concrete for the 4<sup>th</sup> floor, this section, to be placed next Friday, June 1<sup>st</sup>.
- 9. Jim Lanza informed SRG on May 23<sup>rd</sup> that the slab-on-grade is anticipated to be placed Wednesday, May 30<sup>th</sup>.

**Diagrams:** (Attached Photos 1 through 23)

C: File

Signed: \_\_\_\_\_