August 29, 2008

Nelson E. Collins, Supervisor Licensing & Inspections Unit State of Maine Department of Public Safety Office of State Fire Marshal 52 State House Station Augusta, Maine 04333-0052

Dear Mr. Collins:

Attached is the Statement of Deficiencies and Plan of Corrections for the deficiencies identified during the Fire Marshal Inspection on August 25, 2008.

I do hope that I have submitted this response in an acceptable format. Should you have any immediate questions, please contact me directly at 207-879-3574 or connollym@mercyme.com.

On behalf of Mercy Hospital, I thank you for your time and efforts.

Sincerely,

Michael Connolly

Director of Plant and Engineering

Mercy Hospital

144 State Street

Portland, ME 04101

cc: Eileen

Eileen Skinner, President and CEO

Robert Nutter, VP of Human Resources and Support Services

Rhonda Lanzara-Dalfonzo, RN Quality Specialist

Timothy Prince, VP of Planning and Ancillary Services

Jon Klages, Fire Marshal Inspector

Capt. Greg Cass, Portland Fire Department

Mike Collins, Portland Building Department



Maine Department of Public Safety State Fire Marshal's Office 52 State House Station Augusta, Maine 04333-0052



Anne H. Jordan Commissioner

Chief John C. Dean State Fire Marshal Fax 207-287-6251

Phone 207-626-3880

Statement of	of Deficier	icies and Pl	an of Cor	rections

Facility Name: Mercy Hospital	Owner Name:
Location:	Address:
Facility Type: Hospital	
Telephone: Resource ID:	
During an inspection of your facility a certified State Inspector has found the following violations.	In this right hand column you are required to indicate how and when you will have these violations corrected. Complete this information and return this "Plan of Correction" to the above address within 10 days of receipt of this statement.
This inspection was conducted at the request of Mercy Hospital. This is not a Federal Health Care Survey. The building is a five story Type I(332 construction.	
General Notes:	
A. Provide flame spread rating for all wood paneling in facility	A. GELBANE WELL SEND to FM OFFICE
B. All electrical panels must have breakers marked as to use or marked spare.	B. PANELS WILL BE MARELED BY 9/12/2008
C. Provide information on rating of all fire doors with piano hinges on them.	C GILBANE WILL SEND TO FM OFFICE ON 9/2/2008
D. Provide Medical Gas certification when done.	D. GELBANE WELL SEND THE TO THE FILE MARSAL OFFICE BY 9/21/2001
E. Provide statement from both Fire Alarm Company and Sprinkler Company that systems are working in accordance with applicable code.	E. GELBANE WELL SEND TO FM OFF.

THIS

GROUND FLOOR

- 1. Room SGE-01 Repair sprinkler pipe penetration to corridor wall.
- 2. Stair well area at SSGST-101. Area under stairs must be sealed to retain two hour rating of stair tower.
- 3. Verify door rating to room SG-008. NOTE: This will be required for all piano type hinges on any rated door that is not clearly labeled.
- 4. Room SGM-01 repair fire proofing on steal structure above fire damper.
- 2. THIS ITEM HAS BEEN COMPLETED.

 3. ALL FIRE RATES DOOPS WELL

 5E TAGGED BY 9/21/2008

 4. THIS ITEM HAS BEEN COMPLETED.

COMPLETED.

Date of Inspection: 25 August 2008

Owner/Occupant Signature

Inspector: Jon Klages



Maine Department of Public Safety State Fire Marshal's Office 52 State House Station Augusta, Maine 04333-0052



Anne H. Jordan Commissioner

Chief John C. Dean State Fire Marshal Fax 207-287-6251

Phone 207-626-3880

Statement of Deficiencies and Plan of Corrections
Owner Name:

Facility Name: Mercy Hospital	Owner Name:
Location:	Address:
Facility Type: Hospital Telephone: Resource ID: During an inspection of your facility a certified State Inspector has found the following violations.	In this right hand column you are required to indicate how and when you will have these violations corrected. Complete this information and return this "Plan of Correction" to the above address within 10 days of receipt of this statement.
6. SG-040 Service air compressor is protruding into the exit door. Change exit door so the right side door has exit hardware and becomes the exit path. Mark the area to prevent buildup of storage that would block the door.	6. Doors WELL BE REPLACED BY 10/26/2008. FLOOR WELL BE MARKED BY 10/26/2008.
7. Fire Pump room GG-042 repair sprinkler pipe penetrations in wall to Central supply	7. THIS ITEM HAS BEEN COMPLETED.
FIRST FLOOR 1. Adjust smoke door SIX100 to close and latch	1. THIS ITEM HAS BEEN COMPLETED.
2. S1-001 (main Lobby) Remove or disconnect gas from non-vented fuel fired heater. This is per Chapter 20 of State Fire Marshal Rules.	2. THIS ITEM HAS BEEN COMPLETED.
3. S1E-01 Repair penetrations to corridor	3. THES EVEN HAS BEEN COMPLETED.
4. Stair one first floor landing repair sprinkler penetration S1ST01	4. THIS ZTEM HAS BEEN COMPLETED.
5. S1-E02 Rate wall behind electrical conduit	5. THES ETEM WELL BE COMPLETED BY
6. Repair shaft access to smoke damper in corridor S1X0440 <i>★ S I X o 4 o</i>	6. THIS ITEM HAS BEEN COMPLETED.
7. Stair two first floor S1ST02 repair pipe penetrations	7. THIS ITEM HAS BEEN COMPLETED.
8. Repair penetrations in rooms; 2047, 2045, and 2032, 2019.	8. THIS ITEM HAS BREN COMPLETED.

Date of Inspection: 25 August 2008

Owner/Occupant Signature

Inspector: Jon Klages



Maine Department of Public Safety State Fire Marshal's Office 52 State House Station Augusta, Maine 04333-0052



Anne H. Jordan Commissioner Chief John C. Dean State Fire Marshal Fax 207-287-6251

Phone 207-626-3880

Statement of Deficiencies and Plan of Corrections

Facility Name: Mercy Hospital	Owner Name:
Location:	Address:
Facility Type: Hospital	
Telephone:	
Resource ID:	T. 41:
During an inspection of your facility a certified State Inspector has found the following violations.	In this right hand column you are required to indicate how and when you will have these violations corrected. Complete this information and return this "Plan of Correction" to the above address within 10 days of receipt of this statement.
9. IV preparation room must have smoke detection or a door separating it from the corridor. If the us of the space involves treatment then a door will be required.	9. THIS ITEM WILL BE COMPLETED BY 9/21/2008.
Third Floor	
1. Repair steal beam with required fire spray to return beam to two hour rating in room S3025	1. THES ITEM HAS BEEN COMPLETED
2. Stair one-third floor repair penetrations in wall.	2. THIS ITEM HAS BEEN COMPLETED
Fourth Floor	
1. S4032 Repair walls to required rating	1. THIS ITEM WILL BE COMPLETED BY 9/5/2008
	2. THIS ITEM HAS BEEN COMPLETED
2. Repair smoke wall in room S4037 around pneumatic tube	
3. In room S4040B repair 1 hour rated wall	3. THIS ITEM HAS BEEN COMPLETED.

Date of Inspection: 25 August 2008

Owner/Occupant Signature

Inspector: Jon Klages



Maine Department of Public Safety State Fire Marshal's Office 52 State House Station Augusta, Maine 04333-0052



Anne H. Jordan Commissioner Chief John C. Dean State Fire Marshal Fax 207-287-6251

Phone 207-626-3880

Statement of Deficiencies and Plan of Corrections

l	Facility Name: Mercy Hospital	Owner Name:
	Location:	Address:
	Facility Type: Hospital	
	Telephone:	
l	Resource ID :	
	During an inspection of your facility a certified State Inspector has found the following violations.	In this right hand column you are required to indicate how and when you will have these violations corrected. Complete this
	has found the following violations.	information and return this "Plan of Correction" to the above
İ		address within 10 days of receipt of this statement.
ı		address million to days of receipt of this statement.

This inspection was conducted at the request of Mercy Hospital. This is not a Federal Health Care Survey. The building is a five story Type I(332 construction.

General Notes:

- A. Provide flame spread rating for all wood paneling in facility
- B. All electrical panels must have breakers marked as to use or marked spare.
- C. Provide information on rating of all fire doors with piano hinges on them.
- D. Provide Medical Gas certification when done
- E. Provide statement from both Fire Alarm Company and Sprinkler Company that systems are working in accordance with applicable code.

GROUND FLOOR

- 1. Room SGE-01 Repair sprinkler pipe penetration to corridor wall.
- 2. Stair well area at SSGST-101. Area under stairs must be sealed to retain two hour rating of stair tower.
- 3. Verify door rating to room SG-008. NOTE: This will be required for all piano type hinges on any rated door that is not clearly labeled.
- 4. Room SGM-01 repair fire proofing on steal structure above fire damper.

Date of Inspection: 25 August 2008 Owner/Occupant Signature

Inspector: Jon Klages Date:



Maine Department of Public Safety State Fire Marshal's Office 52 State House Station Augusta, Maine 04333-0052



Anne H. Jordan Commissioner Chief John C. Dean State Fire Marshal Fax 207-287-6251

Phone 207-626-3880

Statement of Deficiencies and Plan of Corrections

Facility Name: Mercy Hospital	Owner Name:
Location:	Address:
Facility Type: Hospital	
Telephone:	
Resource ID:	
During an inspection of your facility a certified State Inspector	In this right hand column you are required to indicate how and
has found the following violations.	when you will have these violations corrected. Complete this
	information and return this "Plan of Correction" to the above
	address within 10 days of receipt of this statement.

- 6. SG-040 Service air compressor is protruding into the exit door. Change exit door so the right side door has exit hardware and becomes the exit path. Mark the area to prevent buildup of storage that would block the door.
- 7. Fire Pump room GG-042 repair sprinkler pipe penetrations in wall to Central supply

FIRST FLOOR

- 1. Adjust smoke door SIX100 to close and latch
- 2. S1-001 (main Lobby) Remove or disconnect gas from non-vented fuel fired heater. This is per Chapter 20 of State Fire Marshal Rules.
- 3. S1E-01 Repair penetrations to corridor
- 4. Stair one first floor landing repair sprinkler penetration S1ST01
- 5. S1-E02 Rate wall behind electrical conduit
- 6. Repair shaft access to smoke damper in corridor \$1X0440
- 7. Stair two first floor S1ST02 repair pipe penetrations
- 8. Repair penetrations in rooms; 2047, 2045, and 2032, 2019.

Date of Inspection: 25 August 2008

Date:

Inspector: Jon Klages

Owner/Occupant Signature



Maine Department of Public Safety State Fire Marshal's Office 52 State House Station Augusta, Maine 04333-0052



Anne H. Jordan Commissioner Chief John C. Dean State Fire Marshal Fax 207-287-6251

Phone 207-626-3880

Statement of Deficiencies and Plan of Corrections

Facility Name: Mercy Hospital	Owner Name:
Location:	Address:
Facility Type: Hospital	
Telephone:	
•	
Resource ID:	
During an inspection of your facility a certified State Inspector	In this right hand column you are required to indicate how and
has found the following violations.	when you will have these violations corrected. Complete this
0	information and return this "Plan of Correction" to the above
	address within 10 days of receipt of this statement.

9. IV preparation room must have smoke detection or a door separating it from the corridor. If the us of the space involves treatment then a door will be required.

Third Floor

- 1. Repair steal beam with required fire spray to return beam to two hour rating in room S3025
- 2. Stair one-third floor repair penetrations in wall.

Fourth Floor

- 1. S4032 Repair walls to required rating
- 2. Repair smoke wall in room S4037 around pneumatic tube
- 3. In room S4040B repair 1 hour rated wall

Date of Inspection: 25 August 2008

Owner/Occupant Signature

Inspector: Jon Klages