

Eleanor & Bill

From: Eleanor & Bill <billie@maine.rr.com>
Date: Monday, September 29, 2014 10:49 AM
To: <gef@portlandmaine.gov>
Cc: <cpizey@gmail.com>
Subject: Fw: RoofDeck @ 7 Veteran ST. , Peaks Island, Me.

From: Eleanor & Bill
Sent: Monday, September 29, 2014 10:14 AM
To: gef@portlandmaine.gov
Cc: cpizey@gmail.com
Subject: Fw: RoofDeck @ 7 Veteran ST. , Peaks Island, Me.

From: Eleanor & Bill
Sent: Monday, September 29, 2014 9:41 AM
To: gef@portlandmaine.gov
Cc: cpizey@gmail.com
Subject: RoofDeck @ 7 Veteran ST. , Peaks Island, Me.

UNCORRECTED COPY

A structural visual inspection of the roof deck was conducted on 9/26/2014. There were no signs of any structural

distress and the deck appears to be in good condition.

RECOMMENDATION :

To further strengthen the header connection at the supporting posts and the house wall: Attach a 2x4 under the deck support header at each post. Shim and attach a 2x4 under the nearest

at the house wall. The 2x4 should extend down to roof pads at the posts.

William Koutalidis, P.E.

