

Permitting and Inspections Department Michael A. Russell, MS, Director

May 20, 2017

KELLY JOHN J & TRACY A KELLY JT 23 WILLOWDALE DR MERRIMAC , MA 01860

CBL: 092 A008001

Located at: 622 ISLAND AVE

Certified Mail

Dear KELLY JOHN J & TRACY A KELLY JTS,

An evaluation of the above-referenced property on **09/16/2016** shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 30 days of the date of this notice. A re-inspection of the premises will occur on 06/24/2017 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

Kevin Hanscombe

Code Enforcement Officer

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date
KELLY JOHN J & TRACY A KELLY JTS		Matthew Sarapas	9/16/2016
Location	CBL	Status	Inspection Type
622 ISLAND AVE	092 A008001	Reinspect	Housing Safety Inspection
Code	Int/Ext Floor	Unit No. Area	Compliance Date

1) 205

Violation:

SMOKE ALARMS / LEVEL; Smoke Alarms - One and Two-Family Dwellings: Single-station or multiple-station (interconnected) photoelectric smoke alarms must be powered by the building electrical system or powered by a 10-year non-replaceable battery and shall be positioned correctly on walls or ceilings: (1) within 21 feet of any door to a sleeping room and (2) in living areas separated by doors on each level of the dwelling unit and (3) including the basement.

NFPA 101 (2009) 24.3.4.1(2)(3), 9.6.2.10, amended by City Code of Ordinances Section 10-3(i)

Notes:

Second floor needs smoke detector

2) 207

Violation:

CARBON MONOXIDE ALARMS / LEVEL; Carbon Monoxide Alarms - One and Two-Family Dwellings: Single-station or multiple-station (interconnected) Carbon Monoxide alarms must be powered by the (A) building electrical system, or (B) 10-year non-replaceable battery and shall be positioned correctly on walls or ceilings: (1) on each level of the dwelling unit, and (2) including the basement.

NFPA 720 (2009) 9.5.1, 9.5.3, amended by State Law Title 25, Chapter 317 § 2468

Notes:

Second floor needs co detector

3) 211

Violation:

OTHER

Notes:

Recommend moving basement detectors to side of basement with combustion devices

Comments: