Project: Bangor Savings Bank, Marginal Way

**Date Prepared: 07/23/2015** 

## Structural Statement of Special Inspections (Continued)

## Final Report of Special Inspections (SSIC/SI 1)

[To be completed by the Structural Special Inspections Coordinator (SSIC/SI 1). Note that all Agent's Final Reports must be received prior to issuance.]

Project: Bangor Savings Bank

Location: Marginal Way Portland, Maine

Owner:

Owner's Address:

Architect of Record:	Daniel C. Miller	TAC Architectural Group
_	(name)	(firm)

Structural Registered Design

Professional in Responsible Charge:

Aaron C. Jones
Structural Integrity
(name)
(firm)

To the best of my information, knowledge and belief, the Special Inspections required for this project, and itemized in the *Statement of Special Inspections* submitted for permit, have been performed and all discovered discrepancies have been reported and resolved.

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted, Structural Special Inspection Coordinator	
Aaron C. Jones	
(Type or print name)	_
Structural Integrity	_
(Firm Name)	
Amon Com	05/20/2016
Signature	Date

