

# Memorandum

---

**To:** Joe Shaffer  
**From:** Mike Nugent/Manager of Inspection Services  
**Date:** 04/14/2004  
**Re:** 364 Forest Ave (114A F001)

---

I have Commenced reviewing the plans for Permit # and have the following questions:

1. On page B101 the handrail on the “enlarged First Floor” plan does not extend 1 foot beyond the top tread.
2. Exterior stairs guards appear to be 36 inches not 42 inches, and need tread and riser dimensions
3. Exterior stairs in climates subject to snow or ice must be protected (section 1014.12)
4. The referenced standard in the Code for Engineered Masonry design is Chapters 1 through 8 of ACI 530.1/ASCE 5/TMS 402, the job spec book cites ACI 530.1/ASCE 6/TMS 602 can you advise?