Portland Fire Department

3/25/2019

COTE, MICHAEL & MATTIE 19 CARLYLE RD PORTLAND, ME 04103 cotem2@aol.com

COTE, MICHAEL & MATTIE 19 CARLYLE RD PORTLAND, ME 04103 cotem2@aol.com

CERTIFIED MAIL

RE: 101 DARTMOUTH ST PORTLAND, ME

118 D017001

Page 1 of 2

NOTICE OF VIOLATION AND ORDER TO CORRECT

To Whom it May Concern,

The City of Portland inspected the above-referenced property on 8/8/2017 and found violations of the City of Portland Code of Ordinances, which are listed on the attached page(s). You are hereby ordered to correct these violations by the dates given on the attached.

A reinspection of your property will take place on 5/1/2019 10:00:00AM.

Please contact the Fire Prevention Bureau at 874-8400 if you have any question about your reinspection. If the violations are not corrected at the time of reinspection, you will be charged a \$150 failed reinspection fee.

If you do not correct the attached violations, then this matter may be referred to the City of Portland Corporation Counsel for legal action, including civil penalties and other legal remedies.

Thank you for keeping the City of Portland safe.

Sincerely,

Captain John Brennan Fire Prevention Bureau City of Portland

NON-COMPLIANCE VIOLATION LIST			
NAME	CODE DESCRIPTION	COMMENTS	Deadline
NFPA 101-4.5.3.2, 7.1.10.1	The means of egress shall remain free and unobstructed.	IMMEDIATELY remove all obstructions to the means of egress Rear exit for third floor apartment has storage in exit path.	8/9/2017
NFPA 101-8.3.3.3	Fire doors must be self- or auto-closing.		9/7/2017
NFPA 101-31.3.4.5; City Code 10-3(i)	Photoelectric, hardwired with battery backup smoke alarms must be provided in every sleeping room, outside every sleeping area, and on every level, including the basement.	IMMEDIATELY install temporary alarms where required. Fully compliant, permanent alarms must be installed by the date given. All bedrooms require a hardwired smoke detector.	9/7/2017
NFPA 101-31.3.2	Boiler and fuel-fired heaters serving more than one dwelling unit must have 1-hour separation or sprinkler protection.	No boiler protection on the two boilers that are in basement.	9/7/2017
NFPA 101-31.2.2.1	1-hour fire rated doors and assemblies required, including self-closing and self-latching mechanisms.	Basement door at top of stairs.	11/6/2017
NFPA 101-31.2.2.1	1-hour fire rated doors and assemblies required, including self-closing and self-latching mechanisms.	All apartment entry and exit doors require 1- hour Fire Doors.	8/8/2018